

APR 0 3 1998

LINEP 2052 PAGE 575


STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

1997 DEC 30 PM > 00

SECTION

LAND CORNER RECORDATION CERTIFICATE

_	Filing Require	ement of Act 74, Mich. P.	A. 1970	JU 111 .	
For corners in			. (Parrie Can	-/
Muskegon	Located In:	Corner Code ##	`	REGISTER OF DEFIN	くぎょう
(County)			•	menner of period	,
1. Public Land Survey	T10N_ R_17W	L 13			
	T R				
	T R				
•	T R			1.00	
2. Property Controlling	S T R				
in Section	S T R				
3. Miscellaneous	S T R		Register of D	eeds Stamp & File Nu	umber
Property in Sec.	S T R				
	·			,	
	Recorded Plat		А В	CDEFGHI	J K L
5. Private Claims	<u> </u>				T
•			ľ	-543	-2-
			3	 	111
Delin II II Di	· ·	l 20	<u> </u>	+- 8-+-910	-1112
	, in a field survey on <u>Ju</u> quirements of P.A. 74, Michigan P.A.			 	+++
	in conformance with regulations an			17-16-15	-14
	ructions of the United States Depart	•	_ 1 1	 	- -
	fa Court of Law and/or that the corne	•		20-21-22-	-2324
	ith the rules of the Michigan Board or re-established, monumented, re-n		0.1		1 1 1
expressed below:	re-established, monumented, re-in	ionamented, recovered, tourit	10	29 28 27	-2625
·	corners, all in the same town an	d range may be recorded	11		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12		
• *			13	32 33 34	
A. Description of original	monument and accessories and	I/or subsequent restoration:		<u> </u>	
South 1/4 Corner	of Section 36, T10N R	L 7 W			
7	ali				
Post set by GLO S	Surveyors in 1837; W Oa	ık 8" N82° E 11L and	W Oak North	15L	
MCDC 10501 - Uda	name Man ' and O to			,	
MORG, 1950 8 WILL	ness Map and Current Wi	ttness Book show not	hing at this	corner	
TODO has IF IF Contact	6 I 1002 B 120 BV N	31. P.15 (5) 0 .	6 3.		
Loke by F F Smith	h, L 1002, P 128, PK Na	all: E 15.05 Cente	r of Monument	: Box; N 25.25'	Spike
* .		in Power Pole;	2E 31.08, 2	oike in Power Po	ole;
B. Description of corner e	evidence found and/or method a	NE 104.50' Spi	.Ke in Power I blishing corner:	ole.	
			,	•	
Found 5/8" Rod in	n Concrete in Monument	Box			
	and the second s			·	-
Have record that	M M Buck; F F Smith an	nd C F Lewandoski ms	ed this corne	٠ <u>٠</u> ٠	
Accepted corner l	based on historical usa	age and documentation	n.	•••	
		<u> </u>			



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" Rod in Concrete in Monument Box

N 72° E 104.24' Found Spike in S Side of Power Pole S 76° E 104.781 Set PK Nail in N Side of Power Pole S 32° E 30.62' Found Spike in W Side of Power Pole S 24° W Set Spike in W Side of 24" Oak Set"+" in S Bolt of Light Pole Base 70.391 N 53° W 75.71 North 25.20' Found PK Nail in E Side of Service Pole EAST 15.65' Found 5/8" Rod in Monument Box, North 1/4 Corner of Section 1 T9N R17W (L 1)

RALPH W. VAN RIPER PROFESSIONAL SURVEYOR NO. 16946 OFESSION!

Signed by ____ 16946

Surveyor's Michigan License No.