REMONUMENTATION

FEB 0 9 2000

Recorded Plat

Property in Sec.

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION	Filing Requirement of Act 14	
SECTION For corners in Muskegon County	Located in:	Corner Code #
1. Public Land Survey	T 12N R 17W	B-7
e.	TR	
2. Property Controlling S in Section S	_ T R	
3. Miscellaneous S_	TK	

Muskegon County Register of Deeds Muskegon, Michigan

Register of Deeds Stamp & File Number

C В

G

Donald G. Sandel in a field survey on April 14, 1999 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,

monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

8-18-17-18-15-14-13		
7-6-1-1-1-1-1-1		
8-19-20-21-22-23-24		
10-30-29-28-27-28-25		
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
12 31 - 32 - 33 - 34 - 35 - 36		
13		
POSITION OF SAID		
RECORDED CORNER		
REVIEWED & RATIFIED		
BY MUCHECON COUNTY		
POER CHOUP IN ACCORDANCE		

White P.A. 345, CF 1930

A. Description of original monument and accessories and/or subsequent restoration:

(1) GLO: set quarter section post, April 4, 1838: Beech 12" N27°E .12 chains; Beech 14" S15°E .14 chains

(2) D. Sandel # 25870 set capped 1/2" iron over plow point on centerline of Eilers Road (E/W Asphalt). N54°W found center GTE Cable Box, 42.63° S04°E found center metal fence post, 31.79'

N24°E set nail SE side power pole, 44.67' \$71°W set nail NE side power pole, 77.90

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1) Found 1/2" Sandel #25870 capped iron 18" long over broken plow point pieces at centerline of Ellers Road (E/W Asphalt). Verified corner location using existing witnesses.

(2) Historical usage, documentation, and evidence of corner location reviewed and ratified by the Muskegon County Peer Group, April 13,1999.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4"D X 31" Cast Iron "County Survey" monument in place of found capped 1/2" iron; witnessed as follows:

\$42°E set nail NE side 13" Poplar, 37.30' * \$36°W set nail NW side 9" Spruce, 35.68" S75°W set nail NW side 11" Maple, 78.94" N68°W set nail S side 24" Maple, 76.97 N28°W set nail SW side 36" Maple, 39.66' N23°E set nail SE side Wooden corner fence post, 39.04 N25°E found nail SE side utility pole, 44,67'

DOMALD G SANDEL **ESSIONA** No 25870 OPUBBION

signed by Surveyor's Michigan License No.