## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	T <u>43 N</u> R <u>26 W</u>
DESCRIPTION OF CORNER <u>North 1/16 corner for Secti</u>	ons 33/34
CORNER MONUMENT 1" iron pipe with h" aluminum cap	)
DATE MONUMENT PLACED AND WITNESSED	)
WITNESSES TO CORNER 4" Tamarack (N1/16) (BT	) \$43°w, 6.5'
1 Tamarack (N1/16) (BT	') N27 <sup>0</sup> W, 24.3'
AND	
CIRCLE CORNER REGISTERED	
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED A	ND IDENTIFIED OR RESTORED.
This corner was set from notes of Marcus MoNabb, Sur	veyor. Spruce 3 1/2" NO50W,
8.5' - rotted and down; scribe marks and axe marks s	till visible. Spruce 4"
N80°W, 16.25' - nothing remains. Corner lies 16.5'	
Broken post and post bottom found.	-
	•
SURVEYOR'S SEAL	
DISTRIBUTION:  SIGNED  REGISTERED LAND SUR  Frank J. Bray	DATE 8-11-72 EVEYOR
	R 4047
	Rev. 1