MAR LE 1999

SECTION

Surveyor's Michigan License No.___

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARGULTTE COUNTY
S HIGHIGAN
PECELYED FOR RECORD

1998 DEC 16 PM 3: 20

De alas

MARQUETTE (County)		Located In:		Corner C	ode#	Ü	REGISTER OF DEEDS				
1. Public Land Surve	_	T <u>45N</u> R <u>25'</u> T <u>44N</u> R <u>25'</u> TR T R	<u></u>	D-13 D-1							
2. Property Controlli		Г R Г R									
3. Miscellaneous Property in Sec.	<u>s</u>	TR TR				Regis	LIBER	R	2 P/	AGE 7	
4. Lot No 5. Private Claims						a P	C D F		и т		
						1 1		F G	ΪΤ̈́	JK	
I, GERALD W. CARL do hereby state that un mentioned in lines 1 an required in the current ma Bureau of Land Manage mentioned in lines 3, 4 a Land Surveyors or by a recovered, found as expen	der requirements of 2 above were to annual of survey instrument or by a defend 5 above were a Decree of a Co	of P.A. 74, M n conformance tructions of the cree of a Coul in conformance	ichigan P.A. with regula United State rt of Law an with the rul	of 1970, to tions and respectively and respectively that to the following the followin	he corner points ules therefore as nt of the Interior, he corner points lichigan Board of	5 — 18—7 — 7 — 7 — 7 — 7 — 7 — 7 — 7 — 7 — 7		9	10	-14	
	esseu below:					8 19	20	21	22	_23	
NOTE: Not more that on this certification	n 2 corners, all i cate.	n the same to	own and rang	ge, may be	recorded	10 30	29	28	27	26	
A. Description of orig D-13: Quarter Corner 1844: William A. Burt' post referenced by:	common to Sect	ion 32, T45N	I-R25W; and	I Section 5	<u>, T44N-R25W.</u>	12 31	32	33	34	35	
	17E, 25 L	10"	Tamarack	N73W,	06 L						
	or page given), ir e S89-28'-34"W led by Gerald W. S Cap equidistant	dicates the control to the S.W. Carlson P.S. con-line betw	orner as a n Corner of Se #24589 in	nonumente ection 32. L. 5, RC p	d corner. Distar No accessories g. 38 indicates	given. no evidence (of original c	orner i	found.	. He set	
1983: A Certificate of 18" rebar with RLS ca	Survey recorded	by Gerald W	. Carlson P.S	S. #24589	in L. 001, SM	Pg. 440 indic	ates the co	orner a	s a se	t 5/8" X	
Corner of Section 32.	Distance S89-28	'-34"W, 263	7.37' to the	S.W. Cor	ner of Section 3	32. Reference	d by d.h. n	ails in:	to the	9 J.E.	
	10E, 3.00' 10E, 15.08'		Cedar Spruce	S73E N60W,	26.67' 8" 8.75'						
B. Description of corn D-13: 1998: No origin Cedar Post 0.8' from i 38, although the beari chains [462'] East from Distance West is 2637	al corner evidence ron. Distances at ng on the 8" Spr n corner). Measu	e found. Found nd bearings to uce is S60W,	nd and acce o 2 remainin not N60W	pted a 5/8 g found re as recorde	" Iron with G. C ferences check d. Checked Line	Carlson Cap # very well wit a Call:(Leave	h those red Swamp Co	orded urse N	in L. 5 . & S.,	5 RC, Pg , 7.00	
Established new refere	I found cap and inent stamped to 50E, 26.69' ences:	ron with a 2	3/8" O.D. al orner. Monu	luminum p Iment is 0. 8"	pe capped with 1' above ground Spruce	a 3 1/4" dia d. Measured : \$60W,	meter alum found refer 8.68' (G	inum t ences:			
6" Tamarack Signer Steel Sign Post Note: Bearing trees ha and stamped B.T. Tage	ve painted face,			2.20' , d.h. mea RATIFIE I	Tamarack suring nails, D BY PEER GI OF 1990 DY GRAN	Due North, ROUP	18.69'		OF MIC		
4.			•	DATE	NOV 2 19	98	#	CAF	RLSON	4 1	