LAND CORNER RECORDATION CERTIFICATE

MARQUETTE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 45N N. R. 24W W.		
2. PROPERTY CONTROLL- ING IN SECTION——	N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	, T N. R E. W.		
4. LOT NO , REC	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- F-13 South 1/4 Cor. of Section 33; Wood Post Spruce 5" N38°E 21 Lks.; Tamarak 8" N49°W 15 Lks.
- E-13 SW Sec. Cor. of Sec. 33; Wood Post Tamarack 12"- N17°E 75 Lks; Cedar 6" N32°W 20 Lks; Tamarack 4" S64°E 28 Lks.; Tamarack 5" S18°W 20 Lks.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- F-13 Found stump of Tamarack O.B.T. showing hack mark and overgrowth on the B.T. blaze. Nothing left above the hack mark. Set Mon. 9.9' S49'E from O.B.T. stump.
- E-13 Found square Cedar post and point of an older post beside it. Not of record but Mea. North and East to known Cors. look good. Searched thoroughly for O.B.T.s but found none. Set Mon. at post.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-13 1" pipe, 4" aluminum cap; 4" Cedar $S26^{0}W$ 2.0'; 7" Cedar $N87^{0}E$ 5.7'; 4" Cedar $N4^{0}W$ 9.2'; 8" Cedar $N73^{0}W$ 10.7'.
- E-13 1" pipe, 4" aluminum cap; 9" Cedar N34^OE 9.4'; 9" Cedar S2^OW 12.8'; 8" Cedar S53^OW 22.8'; 9" Cedar N12^OW 19.4'.

SIGNED BY Lavil B. Babbitt DATE 9-15-83