## SURVEY &

APR 2 8 1995

For corners in

THARQUEITE COUNTY
1.191 5411; 3/34
RECEIVED FOR RECORD

REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 29 PM 1:55 Patricial Montey

Marquette COMMISSIONCated In:			Corner Code ##	REGISTER OF DETRIS				
1. P	rublic Land Survey	_45N _25W T R	J-3	RATIFIED BY PEER GROUP P.A. 345 OF 1990				
		T R T R			54 ) [ 54pt 12,	3494 1994	<u> </u>	i
in S 3. Mis	n Section hiscellaneous	S T R S T R S T R S T R		Re	egister of Dec	LIBER eds Stamp	1 & File 1	PAGE Z
4. L	ot No , Reco	orded Plat			- A B C	DEF		
5. P	rivate Claims				- 2 6 -	-54	G H I	J K (
Mi	chael Mileski	a field survey on	September 94		4 7	89-	10	11
Manag above Court	gement or by a decree of a Co were in conformance with the of Law; established, re-es- seed below:	ons of the United States Departi furt of Law and/or that the corner e rules of the Michigan Board of stablished, monumented, re-m ers, all in the same town and	points mentioned in lines 3 Land Surveyors or by a Deconumented, recovered, for	, 4 and 5 cree of a ound as	7 8 —19 9 10 —30 11 12 —31	-20 - 21 - 29 - 28 - 32 - 33 - 3	-27- -34-	
A. D	escription of original mon	ument and accessories and	or subsequent restoration	on:	1,9	<del>- + - +</del>		
J-3	3; South One-quart	er Corner Section 2;	•					
	See back of form	n.						
		•						
3. De	escription of corner evide	nce found and/or method ap	oplied in restoring or ree	stablishing	corner:			-
J-3	3; South One-quart	er Corner Section 2;						
	Found Mr. Kazi	anka's iron pipe and 4"	aluminum cap in ag	reement	with his ne	ew bearin	ig tre	es.
	•		Gri	d System	Coordinate 1 - NAD 8 er - 2111 N	3	North	

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

J-3; South One-quarter Corner Section 2;

See back of form.



- International Feet = 559987.62983 26146319.73080

igned by 39091 urveyor's Michigan License No.

Units

JAK OCO BEN

- A. Description of original monument and accessories and/or subsequent restoration:
  - J-3; South One-quarter Corner Section 2;

Originally established during U.S. Survey conducted by Martin Hall, D.S. in 1852 and monumented with a spruce pine post witnessed by a

Spruce Pine 8 N60°W 33 lks. and a Spruce Pine 10 S41°E 8 lks.

This corner was remonumented with a 1" iron pipe and jack pine post on 1 May 1942 by the Marquette County Road Commission. Refer to M.C.R.C. field book 712 pages 20 and 28. The M.C.R.C. noted the following new bearing trees:

8" Jack Pine N25°E 18.1' 4" Jack Pine S13°W 37.4'

On 13 November 1968 Edward Kazianka, P.S. recovered the M.C.R.C.'s iron pipe and remonumented the corner with a 1" x 36" iron pipe with 4" aluminum cap. Mr. Kazianka noted the following new bearing trees:

10" Jack Pine S35°W 81 lks. 12" Jack Pine N37°W 65½ lks. Jack Pine stump S17°W 56½ lks.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - J-3; South One-quarter Corner Section 2;

Replaced found iron pipe with 2" I.D. x 30" aluminum pipe with 3" aluminum cap appropriately stamped as to location.

Set 60d spike W/side 10" Jack Pine N14°E91.98' Set 60d spike N/side 10" Jack Pine S69°E65.55'

The above two new bearing trees marked with upper and lower face blazes and scribed "NBT".

Set 60d spike E/side 13" Jack Pine S32°W53.46' (Kazianka NBT)
Set 60d spike NE/side 18" Jack Pine N40°W30.07' (Kazianka NBT)
Location Post South 1.5'