

**SURVEY &
REMONUMENTATION**

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 29 PM 1:55

For corners in

Marquette
(County)

COMMISSION

Located In:

Corner Code ##

Patricia H. Maleski
REGISTER OF DEEDS

1. Public Land Survey	T	<u>46N</u>	R	<u>25W</u>	L-13	
	T	<u>45N</u>	R	<u>25W</u>	<u>L-1</u> ✓	
	T	_____	R	_____	_____	
	T	_____	R	_____	_____	
2. Property Controlling in Section	S	_____	T	_____	R	_____
	S	_____	T	_____	R	_____
3. Miscellaneous Property in Sec.	S	_____	T	_____	R	_____
	S	_____	T	_____	R	_____

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussone
DATE Sept. 12, 1994

LIBER 1 PAGE 210
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Michael Mileski in a field survey on September, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-13; South One-Quarter Corner Section 36;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-13; South One-Quarter Corner Section 36;

See back of form.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13; South One-Quarter Corner Section 36;

See back of form.



Signed by *Michael Mileski*

Date 21 Nov 1994

Surveyor's Michigan License No. 39091