1993

REVISED JAN . 1983

LAND CORNER RECORDATION CERTIFICATES ON JOB NUMBER: 93300 SHEET NO. : 1-376 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code ## Located In: MARQUETTRI 1. Public Land Survey T45N\_\_ R 25W\_ T45N R 24W R R 2. Property Controlling R \_ R in Section LIBER R Miscellaneous S Register of Deeds Stamp & File Number Property in Sec. \_\_ , Recorded Plat \_\_ 5. Private Claims \_ \_ , in a field survey on \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-6: Quarter Corner common to Section 13, T45N-R25W and 1942 - Gregory Shadko of MDNR indicates he set a corner Section 18, T4SN-R24W. 1844; William A. Burt's original at this position according to a survey of the Swanzy Lake survey notes describe the corner monument as a wood post fishing site. No corner accessories were given. His field notes indicate that he set this corner from the G.L.O. referenced by: bearing trees 4\* Spruce Pine S25E, 28 1 3\* Spruce Pine S28W, 37 1 4" Spruce Pine S25E, 28 1 3" Spruce Pine S28W, 37 1 His notes indicate that the SE spruce pine was a staub and the SW bearing tree was a stump. (See reverse side) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 - Found octagonal concrete monument Michigan Conservation Department fish site (1940). Distance South measures 2639.70, distance North measures 2638.07. Left concrete monument as found. Peer group ratification 12-13-93. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1993 - Michigan Conservation Department octagonal concrete monument stamped to identify the corner referenced by nails in: 9 \* Jack Pine \$35W 54.38 ft. OF HICE 9 Jack Pine S82W 54.28 ft. 9 Jack Pine N04E 120.67 ft. GERALD W. 11" Jack Pine N73E 116.36 ft. CARLSON Monument is 1.1 ft. above ground, 15 ft. +/- East of high water mark of a pond. Stamped MCR 1993 (Marquette County Remonumentation) on cap of the existing monument. SURVEYOR No. 24589 Buslow Carleon \_ \_\_\_ Date \_ POFESSIONA urveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

3. 建氯基氯

## Record No. 376

Part "A" Continued:

1942 - MCRC field book # 712 indicates a BT corner. Concrete monument set by Shadko. Spruce Pine BT S28E 28 I is now a dry staub, markings very distinct set by William Burt in 1844. No corner accessories were given. Coordinates for this corner were indicated in the field book.

49,00 p