LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-	:	CORNER CODE NUMBER
I. PUBLIC LAND SURVEY	T. 45N S., I	26W E.	C-9
2. PROPERTY CONTROLL- ING IN SECTION—	,T	E. W.	
3, MISCELLANEOUS PROPERTY IN SECTION	,T ^{N.}	E. W.	
4. LOT NO, RE	CORDED PLAT		
S DDIVATE / LAIMS			

REGISTER OF DEEDS STAMP AND
FILING NUMBER

A. Description of original monument and accessories and/or subsequent restoration:

S.E. Sec. Cor. of Sec. 19

Michigan Department of Conservation Mon. 1" pipe w/4" Br. Cap Set 10-23-51 8" aspen-N 43°E- 46 Lks. 10" aspen-S 58°E- 71 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" pipe with old sq. scribed post on ground nearby. Both 1951 N.B.T.s are down and very rotten. It appears that the Cons. Dept. Mon. either was never set or it was destroyed during a wildlife cutting project in 1975, and the 3/4" pipe set in its place. Set D.N.R. Mon. in place of 3/4" pipe. Aspen N.B.T.'s were not blazed but were scribed in their bark.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

$$\begin{cases} 4" \text{ aspen - N32}^{\circ} \text{ E - 5.6}^{\dagger} \\ 3" \text{ aspen - N52}^{\circ} \text{ W - 11.1}^{\dagger} \\ 4" \text{ aspen - S58}^{\circ} \text{ E - 17.8}^{\dagger} \\ 3" \text{ J. pine - S46}^{\circ} \text{ W - 12.8}^{\dagger} \end{cases}$$

D.N.R. Mon.

SIGNED BY David & Ba CRitt

DATE 9-12-84

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)