MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

1999 DEC 22 AM 11: 23

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich P A 1970

Patricia	A. Manley OF DEEDS OF
REGISTER	OF DEEDS OF

For corners in	9			- D.L.,		(2
MARQUETTE	Located In:	Corner Code #		o a esco	والمكا لمدينها	T. Mari	leren
(County)	Locatoa III.	Comer Code #		Patrice REGIS	TER OF	DEEDS	12
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				•			. S.
1. Public Land Survey	T 45N R 25W	A-6			_		
	T 45N R 26W	M-6					
	TR						
	TR						
2. Property Controlling S_	TR						
in Section S_	TR						
3. Miscellaneous S_	TR		•	1 1050	\mathbb{R}^2	DATE	18:
Property in Sec. S_	T R				•		
			Register	of Deeds	Stamp &	File Nu	ımbeı
4. Lot No, Record	ed Plat				-		
5. Private Claims			ARC	рее	G H	IJK	с т.
			1 1	ŤŤŤ	Ť	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	Ì
			2 6-	- 5 4			<u> </u>
I, GERALD W. CARLSON	in a field europy on	October 27th 19 99 do	3				
hereby state that under requireme	tots of P.A. 74. Michigan F	P.A. of 1970 the corner points	4 - 7	- 8 — — - 8 — — 9—	i	11	 —12-
mentioned in lines 1 and 2 above							
required in the current manual of sur			<u> </u>				
Bureau of Land Management or b				-1716	15	14	13
mentioned in lines 3, 4 and 5 above				- 	- 	 	
Land Surveyors or by a Decree o		ed, re-established, monumented,	8 19	-2021	22	23	24
recovered, found as expressed below	V:		9				
NOTE: Not more than 2 corner	s, all in the same town and	d range may be recorded	1030	29 28	27_	26	 25
on this certificate.	o, as in the same town an	a range, may be recorded			וֹ וֹ		ا
			11				
A. Description of original monu	ment and accessories and/	or subsequent restoration:	12 31	32-33-	34	35	36-
A-6: Corner common to Section			13 RATIFII	ED BY PE	ER GRO	bup !	
1844: William A. Burt's original to	township boundary survey		P.A. 34	5 OF 1999	0		
monument as a wood post refere	inced by:		Ψ.		15		,

1950: Michigan Department of Conservation field notes indicate that their field crews ran

a random line North between section 13 T45N-R26W and section 18 T45N-R25W and set a 1/4 post 7 chains North of the centerline of M-35 and 40 chains North of the starting point. The notes do not indicate the Point of Beginning or give any references to monumentation.

N36W.

32L

1954: Marquette County Road Commission notes from field book 643 indicate a 1" iron pipe with 4" brass cap with the following references:

Red Pine

West,

S34E,

15L (1/4S-NBT)

14" Y. Birch

B. Spruce S72E,

1991: An LCRC by Keith Sackett, P.S.#19006, Liber 5 RC, Page 309 indicates that he restored the corner position midway and on line and monumented with a DNR monument with the following references:

Sugar Maple N20E, 6" Red Maple

Sugar

\$46W.

24.651 12.101

8"

Red Maple Sugar Maple S73E. N39W, 8.85 5.10

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6: 1999: No original corner evidence found. Found and rejected a DNR monument with a 3 3/4" aluminum cap on 1 1/4" O.D. pipe projecting 0.7' above ground. This DNR corner was set using the rejected DNR corner 1/2 mile North. Corner position was reestablished by single proportionate measurement between the Northwest and Southwest corners of Section 18. Distances North and South are 2642.641

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6: 1999: Removed the existing monument and set a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.2' above ground.

Established new references:

13" Twin Oak 15" Oak

N85E. N15W,

28.44 31.25

Red Maple 9"

S. Maple

\$46W. N08W, 22.17 19.26'

Green Steel Sign Post w/ Yellow Survey Marker Sign N17E. 2.27

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

T45N-R25W

Corner Search Report 99100 GERALD V CARLSON SURVEYOR No. 24589

	OFESSIONIL S
Date 12-8-99	
FORM APPROVED BY MICHIGAN STATE BOAR	D OF PROFESSIONAL SURVEYORS, JAN. 28, 19