Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two probable Bearing Trees; a Cedar burned, badly rotted and falled down bearing N46°W 17 Iks., and a Cedar burned and rotted bearing S24°E 22 Iks. Found old blazes to East in line with this corner. Corner lies 1 chain West of Swamp edge.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Billy O. Buckler

DATE 7/29/1964

SIGNED BILLIE A. BOOKTE

REGISTERED LAND SURVEYOR