

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T45-46 NR 29 W

Marquette COUNTY

DESCRIPTION OF CORNER Meander corner between Section's 3 and 34 on East shore
of Long Lake

DESCRIPTION OF CORNER MONUMENT

WITNESSES TO CORNER 9" Cedar N 28 E 43 Links (M.C. NBT)

7" Cedar S 7 W 31 Links (M.C. NBT)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from probable Tamarack B.T. bearing S 72 E, 9 Links.
B.T. down, badly rotted. Found axe marks and overgrowth. No definite scribe
marks.

Found and witnessed while checking lines run by Forestry Division Survey Crew.

Corner was placed and witnessed on 28 July 1958.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 5-15-59
REGISTERED LAND SURVEYOR