MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_45_ NR_29_W_

		_MarquetteCOUNT
DESCRIPTION	OF CORNER	1/4 Corner between Section 2 and 11
DESCRIPTION	OF CORNER	MONUMENT_1" Iron Pipe with 4" Brass Cap
WITNESSES	TO CORNER	7" Oak (1/4s NBT) S 69° E 57 Links
		14" Yellow Pine (1/4s NBT) S 67° W 81 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two stumps in proper positions. The one to NE has log lying near with face on it. Both badly burned.

Corner was placed and witnessed July 16, 1950.

SURVEYORS SEAL

SIGNED SURVEYOR
Billy D. Buckler

DATE _4/28/60_