LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #	
(County)	_		
1. Public Land Survey	TR TR		
2. Property Controlling	S 34 T 45N R 29W	C-E-SE 1/64	
in Section	S 34 T 45N R 29W	14	
	S T R		
3. Miscellaneous	s		
Property in Sec.	s — T — R — —		
			Register of Deeds Stamp & File Number
4. Lot No. , Re	corded Plat		ARCDEFGHTIKI
5. Private Claims	**************************************		1
	07/1	5/2009	2 - 6 - 5 - 4 - 3 - 2 - 1 -
ı, Stephan J. Szyszkoski , in a field survey on 07/1		5/2009 do hereby state	3
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2			
above were in conformance with regulations and rules therefore as required in the current manual of survey ⁵			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13			

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g

(C-E-SE 1/64 cor. Sec. 34) 1/64 corner being the SE corner of the SW 1/4 of the NE 1/4 of the SE 1/4 of Sec. 34. Not established in the original survey.

(14-Sec. 34) South 1/16 corner between Sections 34-35. 1985 - Established by K.L.Sackett RLS midway and on line between Quarter corner north and Section corner south. Set 1"IDx32" I.pipe with 4" alum. 14" J.Pine NO2W 19.1', 5" J.Pine N80E 40.7', 3" J.Pine S01E 14.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-E-SE 1/64 cor.) Established the corner midway and on a straight line between monumented 1/16 corner #13, Section 34 and monumented 1/16 corner #14, Section 34.

(14-Sec. 34) Found the 1985 monument in good condition and at record bearing and distance from the 1985 witness trees J.Pine NO2W (measured as NO2E) and J.Pine NE, both in good condition with scribing visible. I found the monument to have been set at the record position and accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Fd. 1"ID I.pipe with 4" alum. MDNR cap. (1/64) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 18" J.Pine NO2E 19.8' old marks (1985 BT) mrkd "1/64S BT" 8" J.Pine S75W 25.55' 7" J.Pine S47W 18.5' 7" J.Pine N85E 41.0' do 3" J.Pine \$38E 20.55' 3" Cherry S16E 8.8' do 5" J.Pine N79W 18.9' 4" Poplar S65E 17.3' do Set sq'd cedar post adjacent. Set sq'd Cedar post adjacent. Bearings are magnetic. Bearings are magnetic.

Signed by

33986

07/27/2009

do

mrkd "1/16S BT"

do

For the Michigan Department of Natural Resources, Office of Land and Facilities

16278 16279 FORM APPROVED BY MICHIGAN STATE BOAR!

9 10

11

12

(AND Sedise 14. 1975 Sed Jan., 1983 Rervised Oct., 1995

do

OF MICH

STEPHAN J

SURVEYOR

No

ZYSZKOSKI LAND