SURVEY & REMONUMENTATION

MAR 1 3 1998

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

RECEIVED	FOR	RE

SECT	ON
------	----

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1997 DEC 30 PM 1: 45

For corners in MARQUETTE	Located In:	Corner Code #	Patricia d. Monley REGISTER OF DEEDS
(County) 1. Public Land Survey	T <u>46N</u> R <u>25W</u> T <u>46N</u> R <u>24W</u> TR	M-10 A-10	REGISTER OF DEEDS DO
 Property Controlling in Section Miscellaneous Property in Sec. 	TR S T R S T R S T R		LIBER 2 PAGE 58 Register of Deeds Stamp & File Number
	ecorded Plat		
I, GERALD W. CARLSON hereby state that under requestioned in lines 1 and 2 required in the current manual Bureau of Land Managemen mentioned in lines 3, 4 and 5 Land Surveyors or by a De recovered, found as expressed NOTE: Not more than 2 on this certificate A. Description of original M-10: Quarter Corner com R24W. 1844: William A. Burt's ori post referenced by:	corners, all in the same town and monument and accessories and/mon to Section 25, T46N-R25W iginal survey notes describe the	CEMBER 22ND, 19 97, do 2.A. of 1970, the corner points regulations and rules therefore as States Department of the Interior, aw and/or that the corner points the rules of the Michigan Board of ned, re-established, monumented, drange, may be recorded for subsequent restoration: // and Section 30, T46N-corner monument as a wood	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 12 - 13 - 13 - 13 - 13 - 13
10" Sugar S37W	, 20 L 10" Fir	N36E, 23 L	DATE 12/15/97
M-10: 1997: No original control N.E. Corner of Section 36. Line. Various cruisers palline measured 136 feet she decided at the December 1. South of the East 1/4 Cornes Section 1 were proportione East-West position of the I.This put a slight bend in the N.E. Corner of Section 36. The distances West to the	evidence found and/or method apporner evidence found. Survey to the N.E. Corner of Section 1. Interest in the section 1 of the N.E. Comeasurement of 15, 1997 Peer Group meeting to the N.E. Corner of Section 1 and the N.E. Corner of Section N.E. Corner of Section 13 was Performent of the N.E. Corner of Section 1,	control was established along No evidence of existing corne LO Line Calls were tied in along from the N.E. Corner of Section proportion the East 1/4 Corne rner of Section 1. The remain 36. Each 1/2 mile distance W laced 231' West (GLO - 3.5 cl er of Section 13 was placed 28 The remaining stream calls f ion 13 and the South 1/4 Corne	the East Township Line (146N-R25W) from the rest was found along this 5 mile section of Rang the entire 5 mile route. This 5 mile section on 36 to the N.E. Corner of Section 1. It was refered to 1 between the stream call 116' ning of corners South of the East 1/4 Corner of las 2632.72' by using this proportion. The hains) of the centerline of the stream call East. 9.10' West of this calculated straight line from fit extremely well to the proportioned corners. The of Section 24 also fit extremely well to the
M-10: 1997: Set a 2 3/8' stamped to identify the co	rner. Monument is 0.1' above Easterly of tree line of large ma 15.37' 7, 25.09' 7, 30.51' 7, 11.40'	th a 3 1/4" diameter aluminum ground on North slope of hill, i	ng the position of the corner: tablet Marquette County Survey Monument near the Easterly side. Monument is located in ed new references (measures to d.h. nails):

Date