MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_46 NR_27_W

						Marqı	1_0_t_t_0_	COUNTY
DESCRIPTION	OF	CORNER	Seq1	tion co	rner	common to	o_Sections_1	14, 15, 22, 23
DESCRIPTION	OF	CORNER	MONU	MENT.	_ 1"	Pipe with	1 4" Brass (Cap
WITNESSES	то с	ORNER .	15" W.	Pine	_(<u>\$</u>	23 NBT) _	\$ 21° E	09_14nks
			15" W.	Pine	_(<u>s</u>	ī† NĒL)	N_23°_B_	_ 61_Links
			14" W.	Pine _	_(<u>\$</u>	15_NPT) _	_N_40°_W_	_ 93_L1nks
			13" R.	Pine	(8	22 NBT)	s 32° W	115 Links_

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one W. Pine B.T. bearing N 24° W 15 Links. Tree down and in poor condition. Found notch on lower blaze and upper face with overgrowth. Numerous blazes at corner. Found wood post at corner.

Corner was placed and witnessed May 5, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Silly & Suchler DATE 5/23/60
REGISTERED LAND SURVEYOR
Billy D. Buckler