MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T45-46 NR 29 W

				- -	larquette	COUNTY
DESCRIPTION	OF	CORNER	Neander corner	between	Sections 2 and	35 on West side
			MONUMENT			
WITTNESSES	то	CORNER	5" Tamarack	_N_83_E	15 Links, (1	ic met)
			5" Tamarack	_ E 2_W	1 61/2 Links,	(ic iet)

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Tamarack B.T.'s bearing H 25 M, 50 Links and S 22h M, 10 Links. Both B.T.'s down and badly rotted. Found scribe mar s and overgrowth on both stumps.

Corner placed, witnessed and found with Follestry Division Surver Crew on 28 July 1958.

SURVEYORS SEAL

SIGNED

Billy D. Buckler

DATE _4-30-59

REGISTERED LAND SURVEYOR