CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 3/4" iron pipes bearing \$30°W, \$30°E, N30°E, 30.01 from corner.

SURVEYOR'S SEAL

NED _______Billy D. Buckler, R.L.S.

DATE ____ 9=20=1

REGISTERED LAND SURVEYOR