TELEVISION &

APR 0 1 1998

JO: NUMBER: 95053

COMMISSICHAND CORNER RECORDATION CERTIFICATE SH ...T NO. : 1-620 Eiling Beguirement of Act 74 Mich. D.A. 1070

MARQUETTE COUNTY MICHIGAR RECEIVED FOR RECORD

1995 DEC 27 AM 7: 44

| r | | ring nequirement of Act 14, Mich. F.A. 1910 | | | | | |
|----|---|---|---|---------------|---------------|--|-------------|
| | Or corners in MARQUETER MARQUETER (County) | Located In: | | Corner Code # | | Patricia REGISTE | A. Monley |
| 1. | Public Land Survey | Т | R ^{26W} R ^{25W} R | M-5 | | ٠. | ` |
| 2. | Property Controlling in Section | ST | | | | | 1 PAGE 238 |
| 3 | Miscellaneous | ST | | | | LIBER | I PAUL COC |
| | Property in Section | s T | | | Register of D | eeds Stamp & | File Number |
| 4. | Lot No. | , Recorded Plat | | | A D | 0 0 5 5 6 | |
| Ł | Private Claims | | | | <u></u> | | |
| | | | | | 2 6 | | |
| | | • | | | 3 | | |

GERALD W. CARLSON Thursday, November 9 _ , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current n inual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Ducree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found au expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this cartificate

Description of original monument and accessories and/or subsequent restoration:

M-5: Section Corner common to Sections 12 and 13, T47N-R26W unknown surveyor, presumably from original B.T.'s. One and Sections 7 and 18, T47N-R25W. 1844: William A. Burt's probable B.T. in place, poor condition. Referenced by: original survey notes describe the corner monument as a wood post referenced by:

8" Y. Birch \$35W, 27 1

15" Y. Birch N72E, 29 1

1951: A Land Corner Record in Record of Surveys Book #1, Pg. #1, Pg. 57. 57, recorded by the Michigan Department of Conservation

14" Y. Birch S80W, 19.14' 8" Cedar N75E, 32.34' Recorded by Dean C. De La Mater RLS #05778.

1951: MCRC F.B. #651 (No page given) indicates the corner and references as recorded above in Record of Surveys Book

1989: The corner is indicated on two Easement Description Forestry Division, indicates the corner as a set 1" pipe with Maps recorded by Sundberg, Carlson, and Associates in L.

4" Brass Cap. Comer had been placed previous to 1927 by 130, MR Pages 755 & 756. No accessories given. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found and accepted a 1 1/4" galvanized pipe with 4" dia. brass cap, 1.47' above ground. Also found a 3/4" dia. iron pipe with threaded elbow, S27W, 0.69' from monument, and an old, broken, and squared wood post lying next to existing corner. Line call (1.0 ch. North Enter Swamp) measured @ +/- 70'. Line call (6.0 ch. North Leave Swamp[396']) measured @ +/- 395'. Distance North is 5254.76', and Distance South is 5254.01'.

MATIFIED BY PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Measured existing references to found 4" Brass Capped Monument: 20 " Y. Birch Stump w/Scribed Butt Blaze 19.05' (Face) S83.5W, (M.D.O.C. N.B.T.) 11" Cedar 32.50' (Face) S89E. 9" Balsam N66W, 2.88' (Face) Maple 11" NOTE, 8.60' (Face) Established new references with duplex nails set in: N65W. 3.23 7" Halsam MCOM 22.56 12" Balsam S20E. 33.14 10" Balsam SO2W. 24.83 Green Steel Sign Post w/Survey Marker Sign NOOE, 1.0

_ Date _

GERALD W CARLSON SURVEYOR No.

Surveyor's Michigan License No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975** REVISED JAN., 1983