SECTION

For corners in

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUE	TIE COUNTY
RECEIVED	FOR RECORD

199y	DEC	22	111	li.	ረሳ አ
4777	ひじし	27	AM	11:	70

			•
111		1	
Totalin	1	CM	A
o white many and a	GC +	11/1000	اروب 4.
Patricia RFGISTER	rir.	DEEDE	110
	3,2 4	れたどれる	N.
		•	X

MARQUETTE	Located in:	Corner Code #
(County)	· · · · · · · · · · · · · · · · · · ·	
1. Public Land Survey	T <u>47N</u> R <u>25W</u> T R T R	<u>C-13</u>
2. Property Controlling in Section	STR STR	
Miscellaneous Property in Sec.	S T R S T R	
4. Int No. Re	annidad Plat	

LIBER R2 PAGE 217

Register of Deeds Stamp & File Number

GERALD W. CARLSON , in a field survey on <u>November 4th</u> hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: C-13: Corner common to Sections 31 and 32, T47N-R25W on the South Township line. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by:

Spruce Pine N75E,

12L

5" Spruce Pine N17W,

2 3 4 5 8 10 13 RATIFIED BY PEER GROUP P.A. 345 OF 1990

DATE

1986: A survey calculation sheet by Gerry Carlson, P.S. #24589, indicates the corner location distance N89-56-19W, 2635.77' to an existing monument at the South quarter corner of Section 31, distance S89-56-19E, 5271.54' to a DNR monument at the section corner common to Sections 32 and 33, and distance NO0-11-23W, 5309.92' to an iron pin at the section corner common to Sections 29, 30, 31, and 32, T47N-R25W.

1986: A section breakdown calculation sheet by Gerry Carlson, P.S. #24589, indicates the corner location with the same information as above.

1990: An easement map by Sundberg, Carlson and Associates, Inc., indicates a corner. No description or accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-13: 1999: No original corner evidence found. Corner position established by single proportionate measurement on a latitudinal curve between the Southwest corner of Section 31 and the Southeast corner of Section 32, T47N-R25W. Distances are 2636.31' West and 2636.30' East along the South Township Line of T47N-R25W to the South quarter corners of Sections 31 and 32. The Northeast corner of Section 6, T46N-R25W is West 23.76'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-13: 1999: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.10' above ground. Referenced by:

S05W, 3.041

Jack Pine

NO2E,

57.94

9" Jack Pine S42E. 36.531

Jack Pine N.E. Corner Section 6 (cc) S02W. N90W, 71.88' 23.76

6" Jack Pine S20W. 52.831

Green Steel Sign Post w/ Yellow Survey Marker Sign Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

October Search Sheet 99100

Bk. 12, Pg. 94 Bk. 12, Pg. 140-141

GERALD W CARLSON SURVEYOR

No. 24589

Busto value

_ Date 12-5-99