## SURVEY & REMONUMENTATION

APR 2 8 1995

\_\_\_ , Recorded Plat \_

JOB NUMBER: 94030 SHEET NO. : 1-522

For corners in

Lot No.

Private Claims \_

LAND CORNER RECORDATION CERTIFICATE COMMISSION Requirement of Act 74, Mich. P.A. 1970

MARGULI			
MIC	HIGA	H	
RECEIVED	FOR	RECORD	

1994 DEC 28 PN 5: 58

Patricia REGISTER	Å.	6	1	le.	
REGISTER	UI.	Įψ	EDS	6	5,

	MARQUETTE (County)	Located In:	Corner Code ##	REGIS		
1.	Public Land Survey	T 47N, R 26W	<b>G-1</b>			
		T R T R		·		
2.	Property Controlling in Section	S T R S T R				
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds S		
Ì	<del> </del>					

egister of Deeds Stamp & File Number													
		A	В	С	D	E	F	G	н !	IJ	K	L	<u>M</u>
_	2	_	6 —		] 5—		4 —		3 —			,	
	3		_		<u> </u>			Щ		L	<u> </u>		
	4	L	 7—	L	 8—	L,	 	Ļ	0—	_1	1_	1	2_
	5			L		<b>.</b>			<u> </u>				Ш
	6	L,	  8—	Ļ,	   7	L,	[ 6—	1	 5—-	1	4	1	3_
	7	_	_	<u> </u>	<u>L</u>		<u> </u>		<u> </u>		<u> </u>		
		ı	1		1		l		i				

GERALD W. CARLSON in a field survey on Wednesday, December 21 1994 obereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-1: Section Corner common to Sections 3 and 4, T47N-R26W. 1932: Marquette County Road Commission field notes book 1845: Sam Hill's original survey notes describe the corner 451, indicate a Northeast Corner of Section 4 as an iron monument as a wood post set 48.5 1 East of the Section Corner common to Sections 33 and 34, T48N-R26W and referenced by:

pin 1-1/2" diameter on side of 3" strap iron. No corner accessories given. (See reverse side)

S10E, 37 1 6" Fir. Sugar, S40W, 28 1

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner position established at GLO offset 33.07' East of the Southwest Corner of Section 34 and on line between the Southwest and Southeast Corners of Section 34, T48N-R26W. Distance Wost is 2633.47' and distance East is 2634.08'.

RATIFIED BY PEER GROUP

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

7" Maple N19E 25.30 ft.

10" White Birch S52E 3.42 ft.

9.45 ft. 8" White Birch S35W

8" White Birch N62W 3.64 ft.

Steel sign post SOGW

Monument is 0.3' above ground.

≡urveyor's Michigan License No. .

Bk. 6, Pg. 153

Gerold Carlson

GERALD W. CARLSON SURVEYOR No. 24589

FORM APPROVED BY MICHIGAN STATE BOARD THAT SUBVEY REVISED MAY 14, 1975

## Record No. 522:

## Part "A" Continued:

1969:

Land Corner Record filed by Ray J. Brotherton, describes the Corner common to Sections 33 and 34, T48N-R26W and Sections 3 and 4, T47N-R26W as a 1-1/4" old round iron bar at the corner, referenced by:

6" Sugar,

az. 212-1/2,

11.6'

9" Sugar,

az. 313,

9.7

This record filed in both Townships is in error because the original notes state that there is a double corner at this location.