## SURVEY & REMONUMENTATION

MARQUETTE COUNTY								
MICHIGAN								
RECEIVED FOR RECONS								

SHEET NO. : 1-468

For corners in

APR 28 1995 LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

1994	DEC	28	PM	5:	55	
D	4	1	100	,	0	-م

MARQUETTE		Located In:	Corner Code ##		REGISTER OF PERPS					
	(County)				REGIST	ER.OF	DFT	IPS 6	/ <b>\</b>	
1.	Public Land Survey	T 47N R 24	IW E-4		**					
	•	T R				!	,			
		T R				*				
		T R								
2.	Property Controlling	S T R						ě		
	in Section	S T R		LIBE	. D	<b>1</b> PA	<b>1</b>	20		
⇉.	Miscellaneous	S T R			.N aprile Star	JL 7A	UL II.	JUD.	or	
	Property in Sec.	S T R		negister of De	.003 Otal	iib at i		101110	<u> </u>	
				2 6 3 4 7	-\$		3-		-12	
<b>I</b>	GERALD W. CARLSON	. in a field survey on Tue	sday, December 6 199	45		<u> </u>	Ш	_1_	11_	
≡do ≣n ≡cu ■Ma =ab=	hereby certify that under re- lines 1 and 2 above were in trent manual of survey instr magement or by a decree of ove were in conformance with urt of Law; established,	quirements of P.A. 74, Michiga n conformance with regulation fuctions of the United States to a Court of Law and/or that the the rules of the Michigan B.	an P.A. of 1970, the corner points mons and rules therefore as required pepartment of the Interior, Burea corner points mentioned in lines oard of Land Surveyors or by a Difference on the property of the covered.	nentioned 6 18 red in the 7 3, 4 and 5 8 ecree of a 9 found as	-20	21	15	—14— —23—	24-	
■ex	pressed below:			10 - 30	—2 <sup>1</sup> 9——2	28	27—	26	25-	
<b>INC</b>		•	wn and range, may be record	111	++	┼╼┼┈	+	_	<del>   -</del>	
	on this certificate.	•		12 31	_32	<del>'</del> 3——	34	—35 <del></del>	J36_	

A. Description of original monument and accessories and/or subsequent restoration:

corner monument as a wood post referenced by: 9" Spruce N89E, 11 L 12" Hemlock S45W, 21 L 1965: The East 1/4 Corner of Section 8 indicated on MDOT 1973: Plat of survey by Robert F. Cambensy RLS No. 19616 indicates the West 1/4 Corner of Section 9. No corner

E-4: East 1/4 Corner of Section 8, T47N-R24W. 1845: A. D. 1977: LCRC by William Donnan RLS No. 17518 indicates a Sullivan's original subdivision survey notes describe the found wood post on ground. Reset 1/2" iron pipe from Highway Dept. witness, Referenced by:

3" Poplar S15E, 13.35'

6" Pine N65E, 20,30'

2" Balsam N30W, 15.70'

R.O.W. map, sheet #42. Distance North listed as 2639.88', 1979: Certificate of Survey by Gourdie, Fraser, and Associates, William R. Donnan RLS No. 17618, recorded in Liber 001, Pg. 304, indicates the East 1/4 Corner of Section 8 as a found 1/2" iron pipe. (Continued on reverse side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted GCVN iron and cap No. 27464. Distance North is 2631.83' and distance South is 2639.21'.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 5/8" iron and GCVN cap with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

5 1/2" White Pine S68E 12.78 ft. GCVN NBT

4" White Pine S24W 12.66 ft. GCVN NBT

Balsam N35W 15.68 ft. GCVN NBT

3" Balsam N39E 15.61 ft. GCVN NBT

Green steel sign post West 1.0 ft.

accessories given.

Monument is 0.20 ft. above ground. Butt blazes and BT tags were added to existing NBT's. Bk. 5, Pg. 85

Gusto a Carlon

24589

GERALD V CARLSON

SURVEYOR

REVISED JAN., 1983

Burveyor's Michigan License No.

## Record No. 468

## Part "A" Continued:

1979 Con't: Referenced by:

3" Aspen S15E,

6" Pine N65E, 20.30'

2" Balsam N30W, 15.70'

Distance West listed as 5279.59'.

1964: MDOT found a 2" square post referenced by:

5" Poplar 6" Pine

S15E

13.35'

13.35'

5" Balsam

N65E N<sub>3</sub>0W 20.30'

15.70'