LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

	Filing Requirement	nt of Act 74, Mich. P.A. 19	970 as Amended	
For corners in				
Marquette				
(County)	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T48N R 28W	F5		
-	T48N R 28W	G5		
	TR			
	S TR			
2. Property Controlling	S T R			
in Section	S T R			
3. Miscellaneous	S T R		Register of	Deeds Stamp & File
Property in Sec.	S T R		Number	
(, opercy 200.			ABCDE	FGHIJKLM
4. Lot No, Reco	orded Plat		֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֡֓֡֓֓֡֓	
5. Private Claims			2 - 5 - 5	i
5. Tilvace etains			3	
			4	9-10-11-12
1. Stephan J. Szyszkos	<u>ki</u> , in a field survey on	Sept. 4, 2007	do	
hereby state that under require	ments of P.A. 74, Michigan P.A. o	of 1970, the corner points mentic	oned in	
lines 1 and 2 above were in conf	formance with regulations and ru	es therefore as required in the o	urrent 6 18 17 17	.6
manual of survey instructions of	the United States Department of t	he Interior, Bureau of Land Manag	gement 7	
or by a decree of a Court of Law	and /or that the corner points me the Michigan Board of Land Surve	vors or by a Decree of a Court of	of Law: 8 19 20	2324-
established, re-established, mor	numented, recovered, found as ex	pressed below:	9	
			10 30 29	28 27 25 25
NOTE: Not more than 2 c	orners, all in the same town	and range, may be recorde	ed	
on this certificate.	•		11	
	nonument and accessories and		12 31 32	33 - 34 - 35 - 36
midway and on the Sec 8 S45W 15 links, Suga (G5) Corner common to	common to Sections 9 aretion line between Sect or 10 N52E 28 links. Section 9-10-15-16. Succe 12 N50E 25 links.	ion corners 40.20 cha	ins East and West. S Wells Burt. Set Hem	et Maple post. Sugar
(F5) The original post original corner on the original record, midw (G5) The original post found in a mound of rewhat are likely the covisible. Top of hill poster and blazed tre (5306.4 GLO), 5246.04 North (7920.0 GLO). C. Description of monument (F5) Set 1"IDx32" I.p. Set a measuring nail 9" Maple in clump N42	2E 13.5' mrkd "1/4S N	e not recovered. Found the corner by singlatine between Section Remonumented the corners at record bearing Spruce, found in advanchecks with the original conditions and 15759.54' East (10 established to perpetuate locations (G5) Set 1" firm in a Section 15759.54' Spruce 1587 Section 1587 S	d no evidence of the e proportionate measu corners 2666.26' East er at the position of and distance from the nced stages of decay inal record. A Mead ent section corners a 5841.3' GLO), and to ating the position of the corlox32" I.pipe with 4" mound of rock. Set a 49E 11.4' mrkd "S10 N71E 15 9' do F	rement to the and West. an old post hole rotting remains of with no markings Corp. location are: 5332.52' West 1/4 corner 7903.21' mer: alum. MDNR cap made measuring nail in: NBT"
magnetic. Distances	do	9" Spruce 4" Sugar N Pe Bearings a	\$50W 21.7' "\$16 51W 14.7' "\$9 Note that the side of tree.	NBT" IBT"
Surveyor's Michigan License	U	986	Date	33986 AND SURVEY
				- a a defect as