JUL 0 3 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUET	TE (COUNTY
MIC	HIGA	·N
RECEIVED	FOR	RECORD

1996 DEC -4 AN 10: 11

Patricia REGISTER	A.	Mare	lom	
REGISTER	OF	DEFIDS	Zi,	

MARQUETTE (County)	Located In:	Corner Code #
teodity		•
1. Public Land Survey	T <u>48N</u> R <u>25W</u> TR TR TR	B-9
2. Property Controlling in Section	S T R S T R	
3. Miscellaneous Property in Sec.	S T R S	

)	į
)	

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON	, in a field survey on	JULY	<u>17TH</u> , 1	9 <u>96</u> ,
do hereby state that under requireme	nts of P.A. 74, Michigan	P.A. of 19	70, the con	ner points
mentioned in lines 1 and 2 above w	ere in conformance with	regulations a	and rules the	erefore as
required in the current manual of surve-	y instructions of the United	States Depa	artment of th	ne Interior,
Bureau of Land Management or by	a decree of a Court of L	aw and/or t	hat the con	ner points
mentioned in lines 3, 4 and 5 above v	vere in conformance with	the rules of	the Michigar	n Board of
Land Surveyors or by a Decree of	a Court of Law; establish	hed, re-estal	olished, mor	numented,
recovered, found as expressed below:				

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: B-9: Quarter Corner common to Sections 19 and 30.

1845: William Ives' original subdivision survey notes describe the corner monument as a wood post referenced by: N57W. 16 L

22" Hemlock

5. Private Claims

14" Hemlock

S35E,

RATIFIED BY PEER GROUP

Bussn 11/11/96 DATE.

1979: M.C.R.C. field notes by Charles F. Clark P.S. #25836 indicate a 1/2" X 24" rebar & RLS cap witnessed by P.K. Nails in: 07.261

16" Maple 8" Maple

N86E. \$46W.

09.801

12" Maple Fd. 1/2" Iron Pipe

N26W, S82 45'W,

17.87 20.90

2

4

6

٩

11 12

1" Iron Pipe 111.37' (Origin unknown and unrecorded) S87 19'W.

1979: An LCRC recorded by Charles F. Clark PS #25836, in L. 1, RC Pg. 363, indicates that found iron pipes in the area did not conform to corners of record, and that he set a 1/2" X 24" rebar with RLS cap by single proportion measurement between the S.W. and S.E. section corners and referenced as recorded above in 1979 M.C.R.C. field notes (No F.B. or page # shown).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-9: 1996: Searched and found no evidence of original B.T.'s. Found and accepted a 1/2" re-rod, 1.0' tall, with a damaged cap. Found a very old wood post next to iron. Checked Line Call: West, 3.25 chains (214.50'), Small ledge of trapose rock & enter swamp course South and N.E., Measured distance: West, 232'. Checked Line Call: West, 8.75 chains (577.5'), Leave swamp course North & South by West, Measured Call: West 579'. Distance East is 2624.15' and Distance West is 2507.23'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9: 1996: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.5' above ground, and is set on a slope. Referenced by:

9" Maple 15" Maple

S48W, 09.48'

08.121

6" Maple

N12E, 06.331

12" Maple

N43W, 26.30

Green Steel Sign Post w/ Yellow Survey Marker Sign

S88E,

S38W, 01.94'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 9, pp. 97-98.



Gerald W Carlson

Surveyor's Michigan License No.___

Date 12-2-96

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983