SECTION

Surveyor's Michigan License No.

24589

WIS

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY FECHIGAN RECEIVED FOR RECORD

1998 DEC 29 PN 3: 21

For corners in			<i>A</i> .
MARQUETTE	Located In:	Corner Code #	REGISTER OF DEEDS OF
(County)	<del>_</del>		one and difficularly
		1	REGISTER OF DEEDS OF
1. Public Land Survey	T <u>48N</u> R <u>25W</u>	C-10	<b>\</b>
•	T R		
	TR		
	R		
2. Property Controlling	S T R		
in Section	S TR		
3. Miscellaneous	S T B		1/BER R 2 FAGE 106
Property in Sec.	S R		THOUTH TO TAKE TOO
rroperty in occ.	·		Register of Deeds Stamp & File Number
4 1 -4 1/2		<u> </u>	Wellister of Deads Stallip & The Hulliper
4. Lot No, Rec	orded Plat	. <u></u>	
5. Private Claims			
			1 I I I I I I I I I I I I I I I I I I I
		;	2 6 5 4 3 2 1 -
I. GERALD W. CARLSON	, in a field survey on	, 19 <u>98</u> , do	2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
hereby state that under requir	rements of PA 74 Michigan	P.A. of 1970, the corner points	3
mentioned in lines 1 and 2 ab	ove were in conformance with	regulations and rules therefore as	4 - 7 - 8 - 9 - 10 - 11 - 12
required in the current manual o	formular instructions of the Hults	d States Department of the Interior,	
Pursous of Land Management	survey instructions of the Onited	states Department of the Interior,	5
manufactor in the 2.4 and 5.	or by a decree of a Court of L	aw and/or that the corner points	6 18 17 16 15 14 13
mermoned in lines 3, 4 and 5 a	bove were in conformance with	the rules of the Michigan Board of	
		hed, re-established, monumented,	7
recovered, found as expressed by	ælow:		8 19 20 21 22 23 24
NOTE: Not more than 2 co	rners, all in the same town ar	id range, may be recorded	9
on this certificate.		- · ·	10 30 4 29 28 27 26 25
A Description of original m	anument and accession and	lan aubaa aaaa aa aa aa aa a	11
	onument and accessories and	or subsequent restoration:	12 31 32 34 35 36
C-10: Quarter Corner commo			13
1845: William Ives' original s	ubdivision survey notes desci	ibe the corner monument as a	13
wood post referenced by:	•		
10" Maple S29W;	15 L 28" Hemle	ock N25E, 28 L	
1907: The corner is indicated	on highway plans from the l	Marquette County Road	
Commissioners (No Liber or p	g, given). No description of c	orner object or accessories given.	
·			
1958: The corner is shown of	an a Sketch for the Proposed i	Polonotion of County Board 400	ecorded in L. 228, Deeds Pg. 541;L. 228,
Deeds Pa 544: and 1 229	Danda Ba 100 No description	nelocation of County Road 492, R	ecorded in L. 228, Deeds Pg. 541;L. 228,
Deeds Fg. 544, and L. 225,	Deeds Fg. 100. No description	on of corner object or accessories	given.
4004. 4 L000			
1984: An LCRC recorded by	Larry J. Bussone P.S. #2583	3 in L. 4, RC Pg. 385, indicates n	o evidence of original corner found. He set a
1" Re-bar with post midway	between the N.W. and S.W.	Section Corners of Section 29, ch	neck with local Government calls. Referenced
	per and lower notches, uncor	rected compass bearings):	
12" Maple N83E,	7.0' 8" Maple	S02E, 12.7'	
12" Maple S73W,	12.7' 8" Maple	N10W, 8.6'	
	·	•	
B. Description of corner evidence	dence found and/or method a	pplied in restoring or reestablishin	a corner
C-10: 1998: No original corn	er evidence found. Found and	accented a 1" Solid Iron O 64' k	nigh, in good condition, and 0.6' South of fd.
squared wood post with pain	t Rearings and distances to	found references shock well with	h those recorded in L. 4, RC Pg. 385.
Checked Line Call /Stream 3	Course E.C.E. 6 20 [424	OOU shake New to force and A	n those recorded in L. 4, RC Pg. 385.
Morth 2071 to 21 wide street	L, COURSE E.S.E., 0.36 [421.	US I chains North from corner). IV	leasured Call: Measured with hip chain,
North, 267 to 3 Wide stream	n Course E.S.E.; 422' to muc	ky lowland with Cedars at toe of	rise to North. No obvious stream, but water
pockets and noies are presen	t - stream may have changed	its course since time of G.L.O. So	urvey. Distance North is 2611.73 and
distance South is 2613.38'.			
C. Description of monumen	t for corner and accessories e	stablished to perpetuate locating	the position of the corner:
C-10: 1998: Replaced found	l 1" Re-bar with a 2 3/8" O.D	. aluminum pipe capped with a 3	1/4" diameter aluminum tablet Marquette
County Survey Monument sta	amped to identify the corner.	Monument is 0.4' above ground.	Measured found references to set d.h. nails:
12" Maple N83E,	7.27' (Bussone NBT)		S05E, 13.08' (Bussone NBT)
12" Maple S68W,	13.12' (Bussone NBT)	•	
p.:0	TOTAL (Bussons (IB))	o mahia i	N10W, 8.86' (Bussone NBT)
Set Green Steel Sign Post w/	Vollow Curvey Marker Cim	NOSE 2.24	<u> </u>
Set dicen Steel Sign Post W/	reliow Survey Marker Sign	NO6E, 2.94'	The state of the s
N. a. B. a. a. a. a.			Salite of michigan
Note: Bearing trees have pain	ited face, butt, and side nail b	lazes, d.h. measuring nails,	
and stamped B.T. Tags affixe	d.		THE CERTIFICATION AND AND AND AND AND AND AND AND AND AN
		RATIFIED BY PEER GROUP	GERALD W.
		P.A. 345 OF 1990 _	CAKDON 17
		7 7	SURVEYOR *
		- Xami & Busso	No.
		DATE 11/30/98	24589
_	<b>A</b>		
Signed by Husle	0.20		The same of the sa
Signed by	( W Wilson	n 17-2	8.98
		Date	0.78