CREMONUMENTATION

MAY 2 2 1997

COMMISSION

Guella Coulson

Surveyor's Michigan License No. 24589

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAH
RECEIVED FOR RECORD

1996 DEC -4 AN IO: 12

Patricia	A.	Mone	cep
Patricia REGISTER	00	pricos	Sur

MARQUETTE (County)	Located In:	Corner Code #	REGISTER OF DEEDS OF
1. Public Land Survey	T <u>48N</u> R <u>25W</u> TR TR	F-9	
2. Property Controlling S. in Section S. Miscellaneous S. Property in Sec. S.	TR TR TR TR		LIBER 1 PAGE 33
4. Lot No, Record			Register of Deeds Stamp & File Number
I, GERALD W. CARLSON do hereby state that under require mentioned in lines 1 and 2 above required in the current manual of sur Bureau of Land Management or b mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of recovered, found as expressed below NOTE: Not more than 2 corner on this certificate.	ments of P.A. 74, Michigan P were in conformance with re- vey instructions of the United S y a decree of a Court of Law were in conformance with the of a Court of Law; established	A. of 1970, the corner points julations and rules therefore as lates Department of the Interior, and/or that the corner points rules of the Michigan Board of l, re-established, monumented,	5
A. Description of original monu	ment and accessories and/or	subsequent restoration:	11
F-9: Quarter Corner common to 9 1845: William Ives' original subd wood post referenced by: 9" Sugar S60W, 1	Sections 21 and 28. ivision survey notes describe 3 L 18" Hemlock		RATIFIED BY PEER GROUP P.A. 345 OF 1990 Lang Abussine DATE 1/1/196
No Date: MCRC field notes (No F	1/4 Corner of Section 21. N B. # or page given) indicate F.B. #526, pp. 17-20, indicate n U.S. Field Notes and C/L o	the corner as a post 2 1/2' tte the corner as a set stake f Twp. Road running North.	20.0' South of the Center-South 1/16 Cornel West of fence. No accessories given. about 2 1/2' West of fence line, and located Distance S89-50'W, 2635.95' to the Section
B. Description of corner evidence	e found and/or method appli	ed in restoring or reestablishi	ing corner:
those recorded in 1987 by Glenn [69.3'] East of corner). Checked	oximate extension of Vander C. Van Neste, P.S. #27464 call: East, 69.3', intersected there measurement was taker	nboom Road. Distances and I (L. 5, RC Pg. 190). Checked an exposed portion of a mos	O.D. Pipe, 0.2' above ground, +/- 136' bearings to found references check well with Line Calf: (Small Knob of Rock, 1.05 chains of grown-over rock knob, the highest part of 10' higher than surrounding area). Distance
C. Description of monument for	corner and accessories estab	lished to perpetuate locating	the position of the corner:
GCVN washers in: 8" Maple S38W, 19.18'	(Van Neste NBT) (Van Neste NBT) (Van Neste NBT) ow Survey Marker Sign	und. Checked bearings and c 7" Maple N88W, 7" Spruce N24E, South.	slet Marquette County Survey Monument distances to found references with nails and 25.57' (Van Neste NBT) 33.21' (Van Neste NBT) 2.0 GERALD W. CARLSON SURVEYOR

No. 24589

RT A CONTINUED:

59: The Plat of Grandview Subdivision surveyed by R.D. Washburn P.S. #6844, and recorded in L. 12, Plats Pg. 93A, indicates the corner as being 3.4' South of the North R/W line for County Road HA. No accessories or description of comer monument given.

59: Field notes from MCRC F.B. #777, Pg. 3, indicate the corner as a 1/2" circular iron pipe referenced by:

S.W.

07.24

2" Poplar

05.55'

66: The corner is shown on a survey map by Robert D. Washburn P.S. #6844, Book O, Pg. 80. No corner description or accessories given.

73: A Certificate of Survey recorded by Robert D. Washburn P.S. #6844, in L. 1, SM Pg. 56, Indicates the corner as an iron pipe. Distance North,

20.0' to the Center-South 1/16 Corner of Section 21. Referenced by:

Maple

West.

S78E,

25.55' (Tack in N. Face)

4" Maple

\$40W,

19.00' (Nail in N. Face)

75: A Certificate of Survey by Gourdie, Fraser, and Associates, recorded in L. 1, SM Pg. 186, indicates the corner as a found iron. Distance N00-29'-

"W, 5275.19" to the North 1/4 Corner Section 21. Referenced by:

S34W, Maple

18.99 17.84 Maple

S87W.

25.61

376: A Certificate of Survey by Ewart C. Muller P.S. #15408, indicates the corner as a found 1" iron pipe. Measured Distance N89-32'-15"E, 310.04' to a found 1" iron pipe at the S.E. Corner of Section 21. Recorded bearing of same line shown as N89-48'E. No accessories given.

375: An LCRC recorded in 1977 by William R. Donnan P.S. #17618, in L. 1, RC Pg. 192, indicates the corner as a found 1/2" iron pipe (1975)

ferenced by:

W. Pine

' Maple

18.991

5" Maple

S87W,

25.61'

17.84 ' W. Pine S78E,

377: An LCRC recorded by Ewart C. Muller P.S. #15408, in L. 1, RC Pg. 188, indicates the corner as a found 1/2" iron pipe referenced by nails with

W. Pine

S857,

17.83'

S40W, Poplar

19.00

25.60' ' Poplar Due West,

987: An LCRC recorded in 1989 by Glenn C. Van Neste P.S. #27464, in L. 5, RC Pg. 190, indicates the corner as a found 5/8" O.D. pipe in old fence ne on C/L of Vandenboom St. extended, 136' South of the C/L of Co. Rd. 500, and 33.5' West of center of power line. Referenced by:

Maple S36W,

19.17

Maple S89W, 5"

25.54

0" W. Pine N24W,

44.31

Spruce N18E,

33.21