For corners in COMMISSION	of Act 74, Mich. P.A. 1970  Corner Code #  Corner Code #  Corner Code #
4. Lot No, Recorded Plat	A B C D E F G H I J K L M.
5. Private Claims	2 4 5 4 2
	3
GERALD W. CARLSON in a field survey on Thursday, Octobe	4 7 8 9 10 11 12 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 in lines 1 and 2 above were in conformance with regulations and rules there manual of survey instructions of the United States Department of the Management or by a decree of a Court of Law and/or that the corner point 5 above were in conformance with the rules of the Michigan Board of Properties of a Court of Law; established, re-established, monumented, re-modas expressed below:	the corner points mentioned fore as required in the current ine Interior, Bureau of Land is mentioned in lines 3, 4 and ofessional Surveyors or by a ponumented, recovered, found in lines 3, 4 and of land in lines 3, 4 and of l
NOTE: Not more than 4 corners, all in the same town and range, in on this certificate.	nay be recorded 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or sul	Oseguent restoration:
K-6: Quarter Corner common to Sections 13 and 14. 1846: William Ives' original survey notes describe the corner monument as a wood post referenced by:  6" W. Birch S07W, 55 1  2" W. Birch S65B, 23 1  1901: Charles Cummings in Record of Surveys Pages 139 & 141, indicates the corner as an iron pipe set from bearing trees at a distance of 2629.2' North from the S.W. Corner of Sec-	recorded by R. Eddy Matthews, Surveyor, in L. 4, Plats Pg 9. No accessories given. 1925: The corner is shown on the Plat of Russell's Addition recorded by C.C. Hascall, Registered Engineer, in L. 5, Plats Pg. 3. No accessories given. No Date: The corner is shown on the Plat of Ely Park. No Liber and page or accessories given. 1990: An LCRC recorded by Alan Pierce LLS #30097 in L. 5, RC Pg. 265, indicates a found 1 1/4" iron pipe in a water
1995: Found and acceptd a 1 1/4" I.D. pipe, 1.0' below asphal referenced in Part "A" above. Distance West is 5244.18', and	t in monument box, with a possible iron within it as
inward.	,
V Comment	
•	ъ
	P.A. 345 OF 1990
	DATE 04 23, 1995
	·
C. Description of monument for corner and accessories establish	ed to perpetuate locating the position of the corner:
12" W Birch  18" R.Pine  NZ  Set Green Steel Fence Post w/Yellow Survey Marker Sign  Du  Note: Repainted existing face, butt, and nail blazes with dull	Tr. Note: There is concrete in hole below surface with a rap is 0.3' below pavement, and monument lines up with Washers #"30097" in:  1E, 66.92' Pierce N.B.T.  OW, 61.52' Pierce N.B.T.  1W, 50.46' Pierce N.B.T.  e South 42.53'
5K, 11, Pg. 45.	STATE OF MICHIGA
Signed by Gulle a Calson	Date 11-13-95 GERALD W.
Surveyor's Michigan License No. 24589	FORM APPROVED BY MICHIGAN STATE BOADING PROFESSIONAL SIGNIFYING JAN 201397

## Record No. 601:

....

## Part A Continued:

by City of Marquette Engineering Department. Corner is located at the approximate centerline of Fair Ave. and 294' West of Lakeshore Blvd. Corner position established by acceptance of found iron pipe based upon evidence of use by licensed surveyors and verification of ties to the recorded Plat of Ely Park. Witnesses established:

6" R. Maple	N51E,	66.92'
P. Pole	S39E,	40.281
12" W. Birch	S37W,	61.64'
18" R. Pine	N21W,	50.431