SURVEY & REMONUMENTATION

APR 28 1995

JOB NUMBER: 94030

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

1994 DEC 28 PM 5: 58

SHEET	NO.	ŧ	1-517	<i>የ</i> ንግዚ ለዚ	A	C

5. Private Claims __

	MARQUETTE (County)	Located in:	Corner Code ##	Patricia R. Manley of REGISTER OF DETOS OF
1.	Public Land Survey	T 48N R 26W T R R T R R	E-13	
2.	Property Controlling in Section	S T R S T R		LIBER $f 1$ PAGE $f 183$
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No,	Recorded Plat		

, in a field survey on Tuesday, December 27 GERALD W. CARLSON . 1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

6 8 10 11 12 13

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-13: Section Corner common to Sections 32 and 33, T48N-R26W. No date given: Survey map recorded in Liber 271, Page 113. 1844: William A. Burt's original survey notes described the Indicates a Section Corner common to Sections 32, 33 and corner monument as a 14" Cedar. Referenced by:

10" Lynn, N50W, 21 1

No date given: Old CCI field book indicates Southwest Corner of Section 33 with a distance East of 2611.

Sections 4 and 5 in the right of way of the railroad nor No corner accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner position set 24.42' West of found 1 1/2" iron pipe at Northeast corner of Section 5 on line with the Northeast corner of Section 5 and the found R.R. rail at the South 1/4 Corner of Section 33. Distance West is 2647.48' and distance East is 2629.56'.

> RATIFIED BY PEER GROUP P.A. 245 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 5' long, 3/4" diameter rebar capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

5" White Spruce N68W 19.80 ft.

S58W 131.89 fr. White Pine

6" White Birch S04E 137.60 ft. Power Pole S22E 141.10 ft.

Steel sign post N35W 8.25 ft.

Monument is located on an active R.R. grade +/- 1' Northwest of the Northwest rail and is set 1.6' be bottom of the R.R. rail. Bk. 9, Pg. 15

OF MICH GERALD W CARLSON SURVEYOR No. 24589 OFESSIONA

Gerald Cerlas