SURVEY & REMONUMENTATION

APR 2 8 1995

JOB NUMBER: 94030

For corners in

expressed below:

SHEET NO. : 1-521 COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUE	HE (COUNTY				
MICHIGAN						
RECEIVED	FOR	Recond				

1994 DEC 28 PM 5: 58

Patricia REGISTER	D.	Color	l.	
REGISTER	ŋF	PEFNS	0	34,

	MARQUETTE (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OF &
1.	Public Land Survey	T <u>48N</u> R <u>26W</u> T R		
2.	Property Controlling in Section	S T R S T R		1 PAGE 187
3.	Miscellaneous Property in Sec.	S T R S T R	I	Register of Deeds Stamp & File Number
4.	Lot No, F	Recorded Plat		— ABCDEFGHIJKLI
5.	Private Claims			2 6 5 4 3 2 1 3
l	GERALD W. CARLSON	, in a field survey onThursd	day, December 22 19 94	5
do in cu	hereby certify that under re lines 1 and 2 above were i rrent manual of survey instr	equirements of P.A. 74, Michigan P in conformance with regulations ructions of the United States Dep	P.A. of 1970, the corner points mentic and rules therefore as required in partment of the Interior, Bureau of I rner points mentioned in lines 3, 4 a	oned 6 18 17 16 15 14 13-14 13
			rd of Land Surveyors or by a Decree	

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

G-13: Section Corner common to Sections 33 and 34, T48N-R26W. 1969: Land Corner Record filed by Ray Brotherton indicates 1844: William A. Burt's original notes described the corner monument as a wood post at the top of hill, referenced by:

8" Sugar, N40E, 33 1 10" Sugar, N79W, 10 1

on this certificate.

No date given: Old field notes from Cleveland Cliffs Iron Co. indicate the Southeast Corner of Section 33 with a distance

that 1-1/4" old round iron bar at the Corner common to Sections 33 and 34, T48N-R26W and Section 3 and 4, T47N-R26W. Referenced by:

6" Sugar, az. 212-1/2, 11.6'

9" Sugar, az. 313, 9.7

The Corner filed in both Townships is an error because the the original survey notes have double corners at this corner location.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted 1 1/2" iron pipe. Distance West is 2628.72' and distance East is 2645.68'. Section Corner common to Sections 3 and 4, T47N-R26W is East, 33.07'.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

1944

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced a 1 1/2" solid iron with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

White Birch S67E 20.59 ft.

5" Maple \$30W 11.39 ft. Brotherton NBT

Maple N74W 43.12 ft.

N51E 4.00 ft. 9" Birch

Steel sign post S36E 1.75 ft.

Monument is 0.5' above ground.

Surveyor's Michigan License No. .

Bk. 6, Pg. 155

Seeslda Carlson Date

GERALD W CARLSON SURVEYOR No. 24589 ROFESSIONE

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983