			JJ.					
		COMMISS	10N	R RECORDATION				•
	3 NUMBER: 93300 SET NO. : 1-341		LAND CORNE	ER RECORDATION Fement of Act 74, M	CERTIFICATE ich På 1970	• 4 • • • • • • • • • • • • • • • • • •	\$ 5 m	wyr
	or corners in		rung nequi	ement of Act 74, m	ica. r.n. 1910	167 X	R B G	2
****	MARQUETTE (County)	, Loc	cated In:	Corner Code ##			DEC 2	
1.	Public Land Survey	т т	48N R 25W 48N R 26W R R	N-9 V			POR NOT	36
2.	Property Controlling in Section	S T	R R		liher	1 R.C. Pag	7 July 21 July	~~
3.	Miscellaneous Property in Sec.	S T	R			•	Stamp & File N	lumber
4.		•				- A B C C	EFGHI	JKL
5.	Private Claims				##	2 6 5	43	
	<b>;</b>					3 7 8		
do in cu Ma ab	daralo W. Carlson  hereby certify that under the lines 1 and 2 above were intent manual of survey instangement or by a decree over were in conformance out of Law; established pressed below:	requirements of P in conformance structions of the U of a Court of Law a with the rules of the	A. 74, Michigan P.A. with regulations ar Inited States Depar and/or that the corne ne Michigan Board	of 1970, the corner point nd rules therefore as rec tment of the Interior, Bu er points mentioned in lin of Land Surveyors or by a	s mentioned juired in the reau of Land es 3, 4 and 5 a Decree of a	5 6 -1817 7 8 1920 9 10 -3029	21 22	-14 -23 -26
N	OTE: Not more than 4		the same town a	nd range, may be rec	orded	11		
	on this certificat	·e.				12 31 32	3334-	35 3
A.	Description of origina	al monument an	d accessories an	d/or subsequent resto	oration:			
	A-9: Section Corner c and Sections 24 and 2 original survey notes post referenced by: 10* Sugar S75E, 30 8* Sugar N36W, 14	5, T48N-R26W. 1 describe the c	845: William A. E	Burt's indicates the sawood and a post we sawood and a post we saw of the saw	e corner of 2" fith the coordin Clark found a : East 24.5 S05W 14.28 N15W 36.9 (M	ad Commission firon pipe with mates N3.13, E2 1" iron pipe an DSH US-41 plans e reverse side)	stove poker 613.9. d nail & tags i	n
В.	Description of corner	evidence found	d and/or method	applied in restoring o	reestablishing	corner:		
	1993 - Found a 1" diameter pipe. The distance to the West 1/4 corner checks with the Plat of Northwoods Lane Acres and the distance to the South checks with 1940 survey of Section 25 within 11.23 ft. The distance to the South 1/4 corner of Section 19 checks relatively close to G.L.O. The bearing South of this corner bears Southeasterly but the crossing of the lake between the next 2 corners could be the reason for misalignment of the bearings as the original G.L.O. surveyors had to offset around the lake. Replaced the 1" diameter pipe with a Marquette County Survey Monument. Peer group ratification 11-29-93.							
		·						
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:							
	1993 - Replaced 1" di	ey Monument sta				4° diameter alu	minum tablet	
	9" Aspen NO7W 6" White Birch S34E	16.90 ft. Cl	ark NBT				STATE OF MICH	61,0
	8* Aspen S50W 7* Spruce N70W Bk. 3, Pg. 146		ark NBT		,	8+ 8+	GERALD W	1*8

Surveyor's Michigan License No.

24589

FORM APPROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1 REVISED MAY 14, 1 REVISED JAH., 1

Date 12-22-93

SURVEYOR No. 24589

OFEISIONAL

## Part "A" Continued:

## Referenced by nails & tags in:

6" White Birch	S40°E	16.88 ft.
20" Ash	S10°W	14.05 ft.
8" Spruce	N82°W	13.09 ft.
8" Dead Balsam	N12°W	36.93 ft.
L1 RC. Pg. 363		