		· · · · · · · · · · · · · · · · · · ·					
	1993					•	
JOB NUMBER: 93300	COMMISSIÇAND CORNE	R RECORDATION CER	RTIFICATE		48	143	
SHEET NO. : 1-344	Ch. St. Carlotte	ement of Act 74, Mich.		- 77	$C_{i,j}^{n}$:	H C	<u> </u>
For corners in				•	\$ \$35m		
MAROHETTE	Located In:	Corner Code ##	}		1 2 .	는	害亡
(County)	•		-	••	n (. ∵ &	22	
Public Land Survey	T 49N R 25W			•	رون در		1.
1. Public Land Survey	T48N R 25W	M-12 V			100	25	
	T R			8	3, 9	-	* 2.5
	T R				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		_; <
2. Property Controlling					2	GT	
in Section	S T R		Libe	er 1 R.C	Page	23	
3. Miscellaneous	S			ster of Dec	•		Numba
Property in Sec.	S T R	<u> </u>	g.		Jus Otalii		
	•						
	, Recorded Plat			A B C	D E F	GH	ı J K
5 Private Claims							
	•				- 5	1-3-	
•			•	3			1 1 1
				4 - 7	- ė		11
GERALD M. CARLSON	, in a field survey on _ Thursday, requirements of P.A. 74, Michigan P.A.	December 2 , 193.	ationed :	5		-	+++
	ere in conformance with regulations and			618	-1716	1/5	
	nstructions of the United States Depart			7		++	+++
-	e of a Court of Law and/or that the corne			819	-2021-		
	e with the rules of the Michigan Board o ed, re-established, monumented, re-n			9			
expressed below:	a, re-established, monumented, re-n	nonumentea, recoverea, to	uno as	10 30	_292B	27	26
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			ad.	11		li	ĭ
on this certification		id range, may be recorde	:u	12			
on and certific	400			12 31	-3233 	34—	35
A. Description of origin	nal monument and accessories and	d/or subsequent restoration	on:	** h			
	r common to Section 31, T48N-R25W	·		survey in	dicates t	he corse	r
2402502 6024164	,			Cared Air		,,_ ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

referenced by:

16 Sugar S63W, 20 1

25* Sugar N70W, 54 l

Section 36, T48N-R26W. 1845: William A. Burt's original on monument or corner accessories given. His statement in the survey notes describe the corner monument as a wood post survey indicates East from West 1/4 corner on transmission line. There is an East/West power line at this corner. No date given - The Marquette County Road Commission indicates a old iron pipe at fence corner.

(See reverse side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found 1" iron pipe with 1/2" iron inside with RLS cap 17618, Distance North of this corner checks 1.53 ft. short of Marquette County Road Commission in 1940 and checks 2.78 ft. short of Cummings and check exactly with C.C.I. recent survey. Distance South checks 0.11 ft. short of C.C.I. checks 4.73 ft. short of Cummings. Replaced 1" pipe with 1/2" iron with RLS cap 17618 with Marquette County Survey Monument. Peer group ratification 11-29-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Replaced 1" pipe and 1/2" iron RLS cap 17618 with 2 1/8" diameter aluminum pipe capped with 3/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

3rd Power Pole East of road N2 W 23.18 ft.

4th Power Pole East of road N32E 25.96 ft.

6" White Pine

N80E 57.23 ft.

4 Poplar

S60E 75.10 ft.

Monument is 0.7 ft. above ground.

Bk. 3, Pg. 134

Date 12-22

TE OF NICHTS GERALD W. CARLSON SURVEYOR No. 24589 OFESSIONA

Guald W Carlso Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1 REVISED JAN., 1:

Record No. 344

Part "A" Continued:

1972 - William Donnan indicates the corner as a found 1 1/2" iron pipe:

Power Pole N83°W 23.05 ft.
Power Pole N61°W 50.95 ft.
14" Spruce S86°E 62.91 ft.

This corner is not recorded.