For corners in

LAND CORNER RECORDATION CERTIFICATE

	TE COUNTY		
MICHIGAN			
RECEIVED	FOR RECORD		

1999 NOV 18 PM 2: 05

SECTION Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE Located In (County) Ishperning Tow		Potricia de Manhous
1. Public Land Survey T48N T	R <u>27W -05 </u>	Patricia a. Monloy REGISTER OF DEEDS OF
2. Property Controlling ST in Section ST 3. Miscellaneous ST Property in Sec. ST	R	LIBER : R2 PAGE 171 Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		ABCDEFGHIJKL
i, George M. Platz, , in a field state that under requirements of P.A. 74, Michigan P./ above were in conformance with regulations and rules instructions of the United States Department of the In Court of Law and /or that the corner points mentioned rules of the Michigan Board of Land Surveyors or by a monumented, recovered, found as expressed below:	survey on <u>December 7</u> , 19 <u>98</u> do hereb A. of 1970, the corner points mentioned in lines 1 and s therefore as required in the current manual of surve sterior, Bureau of Land Management or by a decree of	2 6 5 4 3 2 1 1 2 2 3 3 4 7 8 9 10 11 12 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13
NOTE: Not more than 2 corners, all in the same on this certificate.	e town and range, may be recorded	9
Section corner common to: Section 10 T.48N. Section 11 T.48N. Section 14 T.48N. Section 15 T.48N.	, R.27W. , R.27W.	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and ac	cessories and/or subsequent restoration:	RATIFIED BY PEER GROUP P.A. 345 OF 1990
1848: Original US Government Survey by S63°E 24 links; 18" Y N57°W 43 links; 10" Y	Pine	DATE 12/14/98
1916 - 1918: Section corner coordinate	information from Cleveland Cliffs Iro conument. No additional information gi	n Company indicates the corner to be a
1990 - 1993: Various survey sketches, C		Outation sheet for breakdown of Section 10
B. Description of corner evidence found and/	or method applied in restoring or reestablishi	ng corner:
of the survey computation sheets by Lar pipe is not in the correct position. The information, holding record CCI distance of section 10. The position achieved by Bussone and Van Neste. Found point fall this calculated position. A stream to 1026'(M). No evidence of original B.T. any other obtained unrecorded survey in	nd no evidence of any other survey montry Bussone, PS 25833 and Glen Van Neste he correct position has been re-calcult es southerly from the NE corner of sectify computing the above fits the intent of ls 79.7' S and 40.8' W of calculated pothe east: 924' (R-GLO), 893' (M); a roo's could be found. All measurements, of formation made available to Spalding Deficiency	ated from record CCI coordinate Lon 10 and easterly from the S 1/4 corner of the computation sheets done by both with. GLO line calls reasonably support tik ledge to the south: 1023'(R-GLO), obtainable recorded survey information and ablecker Associates is documented in the
C. Description of monument for corner and ac	ccessories established to perpetuate locating	the position of the corner:
Set standard Marquette County Remonument aluminum cap stamped with appropriate of	tation Monument, being a 2 $3/6$ " diameteorner identification and "1998 PLATZ 38	er x 30" aluminum post with 3 $1/4$ " diameter 1221". Made the following new witnesses:
Az. 144° 9.43'; Set mag nail w/tag No Az. 225° 16.76'; Set mag nail w/tag No Az. 270° 19.95'; Set mag nail w/tag No Az. 333° 19.30'; Set mag nail w/tag No	o.38121 in S.W. face of a 4" Maple. o.38121 in N.W. face of tree. o.38121 in N. face of a 13" Poplar wi	the position of the corner: er x 30" aluminum post with 3 1/4" diameter 121". Made the following new witnesses: th B.T. tag affixed OF MICHIGATE OF MICHIGATE OF MICHIGATE SURVEYOR No. 38121
Signed by George M. Platz	- Da	ate 12-30 -9 8 0 20 20 10 10 10 10 10 10 10 10 10 10 10 10 10
Surveyor's Michigan License No. 38121		