LAND CORNER RECORDATION CERTIFICATE Filing Peguirement of Not 74 High

MARQUE I		
RECEIVED	FOR	RECORD

For corners in	1 mily requirement of Act 74, with P.A. 1970			19	ÌΫ	NOV	118	3 F	W :	2: 0	6
MARQUETTE (County)	Located In: Corner Code #			79	9. Ja	e Verza	دردن	26	No.	ele.	ورن
1. Public Land Survey	T R			<i>V</i> •	REG	BIST	ER)F D	ÉEC	rle, 15 0	Shir
Property Controlling in Section Miscellaneous Property in Sec.	T R	R	legi							E1	
4. Lot No, Ro 5. Private Claims	ecorded Plat	70				_					
•	1 ·	È	6—		5		4-	H -3		J 2_	K
and 2 above were in confor survey instructions of the L decree of a Court of Law conformance with the rules	in a field survey on December 7, 19 98 do rements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 mance with regulations and rules therefore as required in the current manual of inited States Department of the Interior, Bureau of Land Management or by a and /or that the corner points mentioned in lines 3, 4 and 5 above were in of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; nonumented, recovered, found as expressed below:		7	-1	8	1	9	—10 —15		-11	
NOTE: Not more than 2 on this certificate	corners, all in the same town and range, may be recorded 9	—1 ——	'9 <u> </u>	2	0	2	1	<u>2'2</u>		-2 ¹ 3	
	Section 12 T.48N., R27W. Section 13 T.48N., R27W. 11	3	1-	2	9	—2 —	8	_2 ¹ 7-		-26- -35-	
	monument and accessories and/or subsequent restoration:			IFIE 345				R G	RO	Ï	
848: Original US Gove S51°W N51°E	rnment Survey by Wells Burt - Set wood post witnessed by: 12 links; 14" Fir 25 links; 14" Maple	•	ATI	as		12	115	1/9	78	ے	
564°E N66°E N37°W S43°W	d) and survey computation sheet for survey work done in section 13 by iron with cap. 96.1'; 13" W Pine 116.9'; 13" W Pine 18.2'; 2" Iron Pole 12.8'; Fence Post a sheet by Glen Van Neste, PS 27464. No descriptions or witnesses give	Lai			sone	, P	5 25	<i>/ /</i>	<i>o</i>	7.7.4	

Exiption of corner evidence found and/or method applied in restoring or reestablishing corner:

Iron rod set by Larry Bussone, PS 25833, by single proportionate measurement, per GLO notes, between adjacent corners has been destroyed. A thorough search found no evidence of any other survey monumentation or occupation in the immediate area. Original GLO line calls in the immediate area have been somewhat changed due to a large beaver pond and are inconclusive. No evidence of original B.T.'s could be found. All measurements, obtainable recorded survey information and any other obtained unrecorded survey information made available to Spalding DeDecker Associates is occumented in the research dossier. Considering the above information, we have re-established the 1/4 corner common to sections 12 and 13 by single proportionate measurement, per GLO notes, between adjacent

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Marquette County Remonumentation monument, being a 2 3/8" diameter by 30" aluminum post with 3 1/4" diameter aluminum cap stamped with appropriate corner identification and "1998 PLATZ 38121". Made the following new witnesses:

Az. Az.	93	96.781;	Set PK nail	w/tag no.38121 w/tag no.38121 w/tag no.38121 pe.	in S.W.	face o	£а	2411	White	Pine
------------	----	---------	-------------	---	---------	--------	----	------	-------	------

38121



Date 12-30-98

Surveyor's Michigan License No.

Police Statement and a