## MICHIGAN OCT 2 1005 POLICY DEPT. POLICY DEPT.

FORESTRY DIVISION

## LAND CORNER RECORD

T\_50 NR 28 W.

,		Wardne cre COON I
DESCRIPTION OF	CORNER	1/4_corner between sections 5 and 6
DESCRIPTION OF	CORNER	MONUMENT_10* Spike
WITTNESSES TO	CORNER	12" Hemlock - N 15 W - 42 Links
		20" S. Maple - S 30 W - 31 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was found, and later shown to me, by Mr. Harold Cole, Engineer and Cruiser for Northwestern Veneer and Plywood Corp., who are logging a large area in this township.

One original B.T. still visible, and in fairly good condition. Because this corner fell in a road, we were unable to place our regular corner marker. We placed a 10" spike, 6" below the road surface.

Corner was placed and witnessed September 14, 1950.

SURVEYORS SEAL

SIGNED Sean C. Seon Mater DATE 9/29/50
REGISTERED LAND SURVEYOR