

JUL 0 3 2000

MARQUETTE	COUNTY
MICHIG	
RECEIVED FO	R RECORD

1996 NOV 22 AM 11: 05

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Patricia REGISTER	R.	Mon	law
REGISTER	OF	Dreds	O gr

Marquette	Located In:	Corner Code #	ļ	REGI	STER	OF DI	'EDS #	1. L.
(County)								
1. Public Land Survey	T_50M_R_ T_50M_R_2 TR_							
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_		Regisi	LIBER er of Deed				108 4
4. Lot No, Reco	orded Plat		1 A B	D E	F G	H 1	I J	K L
		Sep 27 1995	3		1			1 -
requirements of F.A. 74, Michig	_, in a field survey on _ gan P.A. of 1970, the corner	, 19 do hereby state that o	under 4 — 7 — ere in _	8-	9	-10	11 	12
United States Department of the that the corner points mentione Board of Land Surveyors or the corner of the corne	Interior, Bureau of Land Mar d in lines 3, 4 and 5 above w by a Decree of a Court of	in the current manual of survey instructions or nagement or by a decree of a Court of Law are were in conformance with the rules of the Mici Law; established, re-established, monume	or the hid/or 6 —18— higan _	17	16	15	—14— ——————————————————————————————————	1.3
recovered, found as expressed t	pelow;		81'9	20	21	-2'2	<u>2</u> 3	24-
NOTE: Not more than 2 co on this certificate.	mers, all in the same town	and range, may be recorded	9 1030	29	28	-27		25

Description of original monument and accessories and/or subsequent restoration: A. Description of original monument and accessories and/or subsequent restablished in 1846 by Austin Burt: "40.00 Set maple (A2) Quarter corner common to Section 6 T50N-R28W and Section 1 T50N-R29W. Corner established in 1846 by Austin Burt: "40.00 Set maple post Qr. Sec. Cor. Hemlock 32 S84E 34, W. Birch 14 N71W 17". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(A2) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner on a straight line between Section corner 2619.47' south and closing corner 2285.48' north, being 40.00 chains, proportionate to the original record, north of the section corner. At the position for the corner, I placed a 1"IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped.

RATIFIED BY PEER GROUP

	DAIE
C. Description of monument for corner an (A2) Set 1" pipe with 4" MDNR cap. Blazed and scribed the following new bearing trees: 12" Sugar N20E 9.2' "1/45 NBT"	d accessories established to perpetuate locating the position of the corner: MDNR monuments are 1"IDx32" iron pipe capped with a 4' dia. cast aluminum Michigan Department of Natural Resources tablet, stamped with Township, Range, corner ID, date of placement, and "PS 33986"
9" Oak N36W 20.9' "1/4S NBT" 5" Hemlock S39E 23.8' "1/4S NBT" 12" Hemlock S61W 27.8' "1/4S NBT" A 16" Cedar, blazed, with signatures and a location poster, was found facing the corner, N21E 21.2'. Bearings are	New bearing trees are marked with a 8H blaze and a lower blaze at the root crown. The blazes are scribed as indicated in quotation marks at left, with NBT or BT (as noted) being on the lower blaze. Distances are horizontal (unless noted) and measured from the corner to the inside of a notch cut into the bottom of the lower blaze.

MICH STEPHAN J SZYSZKOSKI LAND **JRVEYOR** 33986 AND S AN U

Surveyor's Michigan License No.

magnetic.

Date

For the Michigan Department of Natural Resources - Forest Management Division