REMONUMENTATION

APR 1 1 1995

Surveyor's Michigan License No.

Approved by	Menominee County
Land Survey	Remonumentation
	Under Act 345 Of
	4

COMMISSION		LAND CORNE	LAND CORNER RECORDATION CERTIFICATE				PA. Of 1990 On 12/9 199 2			
	COMMISSION	Filing Require				<u> </u>	Mes Envi	4 RLS		
For co	orners in	· · · · · · · · · · · · · · · · · · ·	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-7, 1311-0111		ALTI	Chatrman	- The second sec		
M	IENOMINEE	Located In:	Corner Cod	lo/-/			교육 모	(GE)VED		
	(County)	Loodied III.	0011101 001	10 7 7		I O		Z		
		•	•			n n	12 24 27 27 27			
1. Pt	ublic Land Survey	T <u>33N</u> R <u>27</u> W	H-]	1			3 10	FIG		
		T R				<u>ో</u> లే		<i>→</i>		
		T R				ر ا المراقع ال المراقع المراقع المراق	RIS 4	S		
		T R			İ	હોંડો		record record		
	roperty Controlling S	TR			1		Z 5	•		
		T R								
		TR			Regi	ster of Deeds	Stamp & File	Number		
PI	roperty in Sec. S	T R		· · · · · · · · · · · · · · · · · · ·	L					
4 10	ot No, Recorde	d Diat								
4. Lu	ivate Claims	7		P 11	 ,	ABCD	EFGH	IJKL		
J. 11	TVALE CIGITIS					2 6 5		_ _ 2_		
						3		ШШ		
W	illiam Lenca	M	ar. 22		94	4 7 1				
1	, in a fi		as. 22	19		5				
do here	eby certify that under requiremen		1970, the corner		tioned	6 18 17				
	1 and 2 above were in conform					7	15-13-			
	l manual of survey instructions o ement or by a decree of a Court o						1-1-1-			
_	were in conformance with the rul	•				8 1920	21-22-			
	of Law; established, re-establ					9	+ + + + + + + + + + + + + + + + + + + +	╂╌┼╼┼╌┤		
•	sed below:	•				103029	23-27-	-262		
NOTE:	Not more than 4 corners,	all in the same town and	range, may be	recorded	i '	11	 			
	on this certificate.					12 31-32-	3334	3536		
_						13				
	escription of original monume									
18		ın Mullett - B.T.'s - Tamaı	rack, 10" - N10	W - 12 lk	s; Tamarac	k, 10" - S60 ⁰ W	7 - 36 lks. No) original		
. 10	evidence for this corne		10000	1 -4 - 40						
15		George B. Wilson, RLS No.								
		e proportion method. New nlock - 7.50 feet - 18 deg a					гренцоск - а), /U leet ~		
10		71 by George B. Wilson, F					n 34 and cha	XXX70		
1.7		es to other corners in the se								
	monument 36" long, L		chon. The cor	iici inonui	ment is descr	nocu as a + sq	uare concrete			
	resolution to the state of	pin in venior.								
3. De	scription of corner evidence	found and/or method app	plied in restorir	ng or rees	tablishing c	orner:				
	e recovered the 4" square con									
	nces or signs of well defined o					veral surveys ir	ı the area, it is	5 ,		
ac	cepted as a careful and faithfu	ul re-establishment of the p	position of the o	riginal co	rner.	•	•	W		
								•		
					* *					
٠.					•		•			
		•		•						
					•• •	<u>.</u> ,				
							-			
							· .			
						1 1.				
_			- Litab - C		Saaliuu thii	anaitian of the	corner			
De:	scription of monument for co	orner and accessories est	ablished to pei	petuate ic	ocaung me	position or the	comer.			
Se	et 3-1/4" dia. Aluminum cap s	tamped for corner on exist	ing 4" square c	oncrete me	onument:					
							_			
	8" dia. Tamarack			N12°E	18.27 fee					
	5" dia. Tamarack			N87ºE	17.55 fee					
	12" dia. Tamarack			S05°W	9.13 fee					
	12" dia. Tamarack			S27°W	28.22 fee		T			
	Survey Sign Post			N20°E	2.3 feet		•			

Nov. 21, 1994

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.