Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
PA. Of 1990 On 1993 75

	•	LAND CORNER R	ECORDATION CER	RTIFICATE	Chairman		
		Filing Requireme	nt of Act 74, Mich.	P.A. 1970	_ 53 °		
-01	corners in	_		1	52 S	E C	
		Located in:	Corner Code :///		WIND AND AND AND AND AND AND AND AND AND A	KEOLIVED FOR RECORD	
	(County)	33N 27W	M-1			165 - 71	
1.	Public Land Survey	T R			: ### %	黑	
					温度の重	麗	
		T R T R		ļ		202 201	
ว	Property Controlling S			Company of the Compan	జ్యక్తి ద		
۷.	in Section S				_		
3.	Miscellaneous S	.TR		Registe	er of Deeds Stamp & Fil	e Number	
	Property in Sec. S	.T R	· · · · · · · · · · · · · · · · · · ·	L			
	Lot No, Recorded R	lat			д в с D Е F G H	і і эк ь м_	
4. 3.	Private Claims						
= :	(SAME AS M-13 T34N-R27W; A-	3					
	(SAME AS M-13 13414-02711, 11	,	4	7 - 8 - 910	12-11-12-		
	William Lcnca Oct. 24			95 5			
	, it a field	SP A. 74. Michigan P.A. of 19	70, the corner points me	entioned 6	18-17-16-15	14-13-	
12	The state of the control of the cont	ice with reciliations and ful	62 illeterore as redonc	III III IIIO			
Anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							
		of the Michigan Board of Lar	id Surveyors or by a de	Ciecula a		_ - - - 	
	ressed below:	ed, monumented, re-monu	mented, recovered, it	10	30 29 -28 -27	26-25-	
	TE: Not more than 4 corners, all	in the same town and ra	inge, may be record	ed ¹¹		- - - 	
10	on this certificate.			12	32 -33 -34	35-36-	
		and pagesprine and/or	subsequent restorati	ion:	<u> </u>		
٦,		cription of original monument and accessories and/or subsequent restoration:					
	1848: Original Survey by James	48: Original Survey by James H. Mullett - B.T.'s - Cedar, 8", SW, 13 lks. Tamarack, 10", NW, 31 lks. All original evidence					
	has been destroyed by county road improvements.						
	981: L.C.R.C. No. 302 by William Lenca, RLS No. 26461, states that a 5/8" x 18" Iron Rod was set from information contained						
	in a 1052 graphy by Voith Poborte Surveyor on record with the Menominee County Road Commission, 1125, 5" W.						
	Birch - S38°W - 46.91 fc	Birch - S38°W - 46.91 feet; 9" Tam S87°W - 29.17 feet; Metal Sign Post - N60°E - 51.71 feet; Tel. Cable Box - S18°E -					
	92.22'.						
			-				
3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:						•	
•	:						
In our 1995 remonumentation survey, we recovered the 5/8" x 18" Iron Rod and 9" dia. Tamarack - S87°W						inc whice	
	Birch B.T., Metal Road Sign and Telephone Cable Box have been removed or destroyed. The corner position falls at the PI of a North - South County Road centerline, and in line with the centerline of a County Road running East. This corner has been used by						
	local surveyors for several years, a	nd is accepted as the best	available evidence of	the position of t	he original corner.	·	
	10001 001 10 101 101 101 101 101 101 10	•					
	,						
				•			
			J				
						(COMMON)	
ž.,	Description of monument for corr				Silion of the comercial	OF BICKISCO	
	Set 5/8" x 24" Iron Rod/3-1/4" dia	corner location in Mo	nument Box:	1 S. C.	WILHAM *		
		N7/60F	103 13 feet	Scr. NBT	# :	LENCA	
	10" dia. Tamarack	N76°E S40°W		Scr. NBT	# ·	LAND BURVEYOR *	
	12" dia. Tamarack 10" dia. Tamarack	S40°W S87°W		Scr. NBT		No.	
	10" dia, Tamarack 9" dia, Cedar	N34°W		Scr. NBT		26461	
	Metal Survey Sign Post -	West	27.35 feet		EL SIE	ED LAND SURVEYED	
	• -	NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of					
	NOTE: All bearings are magnetic tree.	gnetic ocarings. All distances are measured with a steet tape. Distances to nees are to half in side of					
	u		-				
	200 mg (10) (Minns	Inco	Date	Oct. 24,	1995		
٠	1					unurvant 189 50 5074	
u	veyor's Michigan License No	40701		FORM AFPROVED I	BY MICHIGAN STATE BOARD OF LAND S	REVISED MAY 14, 1975	
			<u>:</u>			REVISED JAN., 1983	