8 E	

Surveyor's Michigan License No._

Approved	nee County
Poor Group Un	der Act 345 Of
PA 07 1890 On	30 199 8
Mel	SAVIS RIS
Chair	men

49R 0 6 1	999				Miss	SAUIS	RLS
SECTIO		ID CORNER RECORDA ing Requirement of Act 7	TION CERTIF 74, Mich. P.A.	FICATE 1970	PAGI BAR RE	9 =	
MENOMINEE	Located In:	Corner Code #			1000 st	MA	
(County)		oomer oode #			記る	1 0	
1. Public Land Survey	T35NR TR TR				MORRISO MORRISO OF DEEDS E.M. 4985	SECENTED FOR RECEND	
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S TR S TR S TR S TR			- Pagiet	or of Doods N	<u>-</u>	
			<u>. </u>	Negisi	er of Deeds St	amp & Fil	e Numb
4. Lot No, Recor-	ded Plat			3 D		_	
(SAME AS CORNER E-	in a field survey on P.A. of 1970, the corn rules therefore as require therior, Bureau of Land M in lines 3, 4 and 5 above a Decree of a Court of	ed in the current manual of survey fanagement or by a decree of a C	nd 2 above were in Instructions of the ourt of Law and /or	6 -18	5 4 9 17 16 1	-10	J K 2 1111111111111111111111111111111111
NOTE: Not more than 2 come	ers all in the same town	n and range, may be recorded		8 -19	-2021	222	:32;
on this certificate,	oo, as in sie saine low	Tand range, may be recorded		9	29 29	37	
				11 30		272	62.
				12 31	_3233	_343	5
A. Description of original mon		es and/or subsequent restora		13			
1848: Original Survey - N46 ^O W - 05 lks. 1852: Original Survey - S35 ^O W - 12 lks. 1963: LCRC No. 416 (Valks; 8" Elm - (NE) 1989: L.C.R.C. No. 857 from old witnesse	- Township Boundar, All original evidence - Sectional Subdivision All original evidence Vol. 3) by Billy D. Bu BT) - N61 ^o E - 53-1/2 by William Lenca sees." Set 5/8" x 24" In	y - by H. Brevoort, Ir B.T ce for this corner has been of on - by Francis Coleman - I e for this corner has been duckler states: 1/2" x 24" Ir. Iks. No evidence of origin states, "Found 1/2" dia. Iron on Rod / Ident. cap. TIES: Anchor Pole - N28°W - 38 thod applied in restoring or re-	C.'s - W. Pine, 1 destroyed by cou B.T.'s - Hemloc estroyed by cou on bar buried in all corner. a Rod bent over	unty road imports, 18" - S580, inty road import int. of rds N	rovements. E - 13 lks.; He rovementsS-E. TIES: 1	emlock, 8° PP - N44°	E - 73
857 by William Lenca, RL	S No. 26461. The c	corner from information co corner falls in the centerline over 35 years and is accepte	of county road	s North, Sout	h and Fact T	his location	on hac
C. Description of monument for	corner and accessori	ies established to perpetuate	locating the new	sition of the	A CONTRACTOR OF THE PARTY OF TH	William William Henca Hand Sulveyor No.	64
		. Alum. cap stamped for co		PROUGUE OF THE CO	mer:	Down	IN THE PARTY
						dangara	In the
		ked "WITNESS MARKER' 8" dia. Balsam 7" dia. Maple	s 556 ⁰ E	64.58 feet	1' S. of Power Ex. B.T. "X" in upper		
		ked "WITNESS MARKER' 5/8" x 24" Iron Roo Metal Survey Sign Post	l West t West	37.41 feet 33.00 feet 33.6 feet	1' E. of Anche	or Pole	
NOTE: All bearings are m	agnetic bearings. A	Il distances are measured w	rith steel tane	Distances to t	reec um to mai	l in cido o	Ftma

Dec. 22, 1998

Date