APR 06 1999

SECTION

5. Private Claims

on this certificate.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	rvey R	HINORUSIN	intation	
reer es 241990 On	- 4	der Act. 29	345 (# 199	8
,	1	Cil		P

For corners in		C. Chairman
MENOMINEE	Located In: Corner Code #	AGE # ARBA REGIS
(County)		NESAR VICE
1. Public Land Survey	T 34NR 27W G-01	
	TR	NE SERVICE OF THE SER
2. Property Controlling in Section	S TR S TR	550N Y 00
3. Miscellaneous Property in Sec.	S T R	

(SA	ME AS CORNER G	·13, T35N - R27W)		
requirem conforma United State that the dependent of the conformation of the conformat	ents of P.A. 74, Michiga ince with regulations and lates Department of the li corner points mentioned	n P.A. of 1970, the corner rules therefore as required nterior, Bureau of Land Ma in lines 3, 4 and 5 above w a Decree of a Court of	points mentione in the current ma nagement or by a rere in conforman	98 do hereby state that under d in lines 1 and 2 above were in anual of survey instructions of the decree of a Court of Law and /or ce with the rules of the Michigan d, re-established, monumented,
NOTE:	Not more than 2 com	ers all in the same town	and range may	the recorded

- Description of original monument and accessories and/or subsequent restoration:
 - Original Survey Township Boundary by H. Floyd B.T.'s W. Pine, 24" N50°E 21 lks.; W. Pine, 10" N48°W 35 lks. All original evidence for this corner has been destroyed by county road improvements.
 - 1848: Original Survey Sectional Subdivision by James H. Mullett B.T.'s W. Pine, 14" S13°W 14 lks.; W. Pine, 8" S55°E 26 lks. All original evidence for this corner has been destroyed by county road improvements.
 - 1976: Certified Survey Number 59 by George B. Wilson shows this corner as being a 1" round steel pin.
 - 1977: L.C.R.C. Number 161 by George B. Wilson states, "Found old iron pin, Re-set 1" dia. iron x 40" long. This pin will pick up strong on audio meter. Nothing near for ties. This Corner directly tied into Certified Survey in the NE 1/4 of said Section 4."
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" diameter iron rod 36 inches long as described in Land Corner Recordation Certificate Number 161 by George B. Wilson, RLS No. 17607. Existing iron is 2 feet North of the centerline of an East - West county road and in line with the centerline of county roads running North and South. This corner has been consistently used by local surveyors for many years, fits existing occupation, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N38°E	38.50 feet	1' E. of P.P.
	S45°E	47.11 feet	@ Sign Post
	S45°W	42.51 feet	1' W. of Rd. Sign
	N46°W	53.00 feet	1' N. of Tel. Box
Metal Survey Sion Post	S45°E	47.5 feet	2 0 11 0 2 2 3 11 11 11 11

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Frage	Oct. 21, 1998
Surveyor's Michigan License No. 26461	

A MIGI

Leo Lieb