SURVEY & REMONUMENTATION

FEB 1 1 1998

MENOMINEE

1. Public Land Survey

2. Property Controlling in Section 3. Miscellaneous Property in Sec.

(County)

Approved by Menominee County

Land Survey Remonumental	tion
Peer Group Under Act 345	Of
inlin	m 7
1990 Oo <u>/ / ////</u>	733

P.A. Of 1998 On


SECTION	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970
For corners in	1. 1010 Prot 17, Mon. 1 1010

Mich. P.A. 1970 Located In: Corner Code #

. Lot No i. Private Claims	, Recorded Plat	
		

, 19⁹⁷ William Lenca Dec. 02 in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Register of Deeds Stamp & File Number

- A. Description of original monument and accessories and/or subsequent restoration;
 - Original Survey by James H. Mullett B.T.'s Birch, 10" N230W 34 lks.; Birch, 6" S560E 10 lks. All original evidence for this corner has been destroyed by U.S. 41 road construction.
 - SUPERVISOR'S PLAT OF WALLACE by A.L. Hillis shows this corner as the Point of Beginning of the Plat and describes 1924; the corner monument in the Surveyor's Certificate as a 1/2" dia. x 16" iron rod.
 - L.C.R.C. No. 919 by Brian R. Taavola states, "1/2 Inch Copper Clad steel rod with yellow plastic cap embossed "MDOT 1991: 21583" set inside of a monument box, 0.6 FT East of C/L Existing US Highway 41." TIES: Power Pole (nail & tag) -S40°E - 58.38'; S.W. Cor. of Garage Fndtn. - N65°E - 116.12'; Face of ROW Marker @ Ground - West - 50.67'; Street Light Pole - \$550W - 58.03'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found an existing Monument Box with a 1/2" diameter Iron Rod with identification cap marked "MDOT 21583" in a position as described in Land Corner Recordation Certificate Number 919 by Brian R. Taavola. This position fits well with monumentation found in SUPERVISOR'S PLAT OF WALLACE by A.L. Hillis in 1924 and SUPERVISOR'S PLAT OF WALLACE NO. 1 by A.L. Hillis in 1939, and is accepted as the best available evidence of the position of the original corner. of Dichica

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted existing 1/2" dia. Iron Rod inside Monument Box for corner location:

NATO TRUO N680E 5/8" x 24" Iron Rod/2" dia. Alum. cap marked/"WITNESS MARKER" 1.0' N. of Road Sign 47.86 feet 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 3.0' S. of P.P. 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 1.0' N. of P.P. \$430E 62.50 fcct S58°W

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 1.0' E. of Tel. Box Metal Survey Sign Post

57.27 feet N54°W 61.92 fect S430E 63.0 fcct

wu Ham LENCA LAND

NOTE: All bearings are magnetic bearings. All distances are measured with EDM. Distances to trees are to nail in side of tree.

Signed by William Force	<u> </u>	Date	Dcc. 15, 1997
Sunwork Michigan License No.	26461		