## SURVEY & REMONUMENTATION

FEB 1 1 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
Of 1990 On 12/15/1997

	I AND CODNED	RECORDATION CERTIF	EICATD	ex Amis	<u> 122</u>
TION		nent of Act 74, Mich. P.A.		Chairman	
For corners in	i iiiig i toquio		. 1070		
MENOMINEE	h a sata t fau	0 - 1 - 4		933 w	
(County)	Located in: Corner	Code#		3月5日 💆	15.
• •	2431 2737	J-07		· · · · · · · · · · · · · · · · · · ·	- 1
1. Public Land Surve		3-01		\$ \?	
	TR	· · · · · · · · · · · · · · · · · · ·			
	T R	<del> </del>		- 36 E	SINGO FOR REC
2. Property Controllin				- 岩炭 =	975 713
in Section	<u> </u>			÷,,∂ , ∨	
3. Miscellaneous	S TR	<u></u>			
Property in Sec.	S	<del></del>	Register	of Deeds Stamp	& Fil
4 Lat No.	toporded Dist	•			
4. Lot No, F 5. Private Claims	ecorded Plat		1 A B C	DEFGH	1
			2 6	\$	_
		~=	3		
William Lenca	, in a field survey on	$19^{97}$ do hereby state that und		9-10	
	lichigan P.A. of 1970, the corner points menti			+ + + - +	
	ns and rules therefore as required in the current of the Interior, Bureau of Land Management or		ne j	17-16-1-1	
that the corner points men	tioned in lines 3, 4 and 5 above were in confort	nance with the rules of the Michig	an "		
Board of Land Surveyors recovered, found as expres	or by a Decree of a Court of Law; establi- sed below:	ineo, re-established, monumente	ed, 8 19	20217	
•					
	2 corners, all in the same town and range, a	may be recorded	10 30	20 20 2	
on this certificat	<b>⊎.</b>				⊥_'
			11		
	•		12-31	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_
A. Description of origin	al monument and accessories and/or sui	sequent restoration:			
1981: L.C.R.C. N Co. Rd. E	or this corner has been destroyed by countries of the William Lenca states "found with Extended the Countries of the Countrie	iron in line with c/l Co. Rd. nding line & doubling dist.	of Plat Monument	s found in Sup.	Plat c
We recovered a 1/2 iron is 8' +/- south of	er evidence found and/or method applied inch diameter iron 6 inches below the if a newly resurfaced east - west county with established lines of occupation, and	road surface and in line with road centerline. This iron l	a county road cer as been used by le	ocal surveyors fo	r ma
		•		# * / W	KLIA
		•		# : 1	LAND DAND
				<b>∏</b>	PRVEY
C. Description of monu	ment for corner and accessories established for	ned to perpetuate locating the	position of the cor	ner: 🎁 🕏 🐪	No. 3646i
5ct 5/8" x 24" Ifoit.	Kod/3-1/4" dia, Alum, cấp stămped lôr	corner location in Monumei	nt DOX:	BAN 10	**************************************
10" dia, Balsam	(Not blazed)	N110E	115.60 feet	COLUM	COLOR
N.W. Corner of	•	S32°E	55.78 feet		
6" dia. Cedar		S60°W	44.29 feet	Scr. NBT	
	Rod/2" dia. Alum, cap marked "WITN	ESS N50°W	61.43 feet	1.6' W. of P.P.	
MARKER" Metal Survey S	gn Post	South	18.9 feet		
_					
NOTE: All bearing	s are magnetic bearings. All distances	are measured with steel tarx	e. Distances to tre	es are to nail in	side o
	s are magnetic bearings. All distances	are measured with steel tape		es are to nail in	side (
	s are magnetic bearings. All distances	are measured with steel tapx  Date	Oct. 31, 1997	es are to nail in	side