	-	Land Survey Remonumentation Feer Group Under Act 345 Of			
LAND CORNER RECORDATION CERTIFICATE		PA OF 1980 On 12/20 199 25			
For comers in Filing Requirement of Act 74, Mi	ch. P.A. 1970	11/1	-LIAUIS	865	
MENOMINEE Located In: Corner Code =##	1	, TI	Jennight Codec See		
(County)		The second s			
34N 27W K-I1 1. Public Land Survey T R				ن⇔ ر	
T B		; r		FGR	
T R \			5 € E	및 및	
2. Property Controlling S T R		.* (0 1.*	問語不		
in Section S T R		C			
Property in Sec. S T R	Regis	ter of Deeds	Stamp & F	ile Number	
Lot No, Recorded Plat Private Claims		A B C D	E F G	HIJKL	
or Thrace Oranis		2 - 5 - 5	┵╸╅╌┼╌	3	
		3			
William Lenca Jun. 19	95	5		0	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points	mentioned	6 12 17			
in lines 1 and 2 above were in conformance with regulations and rules therefore as requirement manual of survey instructions of the United States Department of the Interior, Bure.	ired in the	7			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			212	2232	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a E Court of Law; established, re-established, monumented, re-monumented, recovered,		9			
expressed below:	1	1 27	2 ¹ 82 ¹	7262	
NOTE: Not more than 4 corners, all in the same town and range, may be recorn on this certificate.	ded 1		72 - 3		
	1	3, 1 %			
A. Description of original monument and accessories and/or subsequent restora	ation:			·	
1848: Original Survey by James H. Mullett - B.T.'s - Y. Pine, 12" - S31°E -		10" - \$67°\	W - 20 lks. A	All	
original evidence for this corner has been destroyed by county road imp 1981: Certified Survey No. 215 recorded by William Lenca, RLS No. 26461, s		r in relation t	o other corn	ers in	
Sections 35 and 36. The survey legend indicates that a 1/2 inch diameter	er iron was found	d. No corner	ties are give	csi.	
1982: Certified Survey No. 303 recorded by George B. Wilson, RLS No. 1760 Section 35. The corner monument is not described and no ties are give:		ner in relatio	n to other c	orners in	
socion 33. The corner monament is not described and no less are given	11.				
P. Description of correct guidence found and/or mathed applied in reglaring or r	aastabliabina aa	****			
 B. Description of corner evidence found and/or method applied in restoring or re- 	eestablishing co	mer:			
In a 1995 survey in Section 36, T34N-R27W, we recovered a 1/2 inch diameter i					
North - South and East - West. This position matches with record distances to so accepted the position of the 1/2 inch diameter iron rod as the best available evide				ı. Wc	
•			_		
			TUTAL TO THE TANK	of MICHIGAN	
•			ART ST.	1.4	
•			.Y .*	IILIAM	
•	•		# = m	LAND IRVEYOR	
	•			No. 2646)	
				ade	
Description of monument for corner and accessories established to perpetuat	e location the or	osition of the	Corner Com	CLAND SUPPLIED	
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Mor		- and it of the			
08.4% - 0.4	, ,				
	_	4 feet – S 6 feet	Scr. NBT		
16" dia. White Pine			cr. NBT		
•	N45°W 62.5	2 fect		•	
Mctal Survey Sign Post	S43°E 47.0	rcct			
NOTE: All bearings are magnetic bearings. All distances are measured with a st	cel tape. Distan	ces to trees a	re to nail in	side of	
tree.				*	

Joseph 26461

Surveyor's Michigan License No. _

Nov. 04, 1995