LAND CORNER RECORDATION CERTIFICATE P.A. 1970

		Filing Requirement of Act 74, Mich.		
Fo	r corners in	-		
	Menominee (County)	Located In:	Corner Code =##	
1.	Public Land Survey	T 35N R 25W	K-3, L-3	
		T R T R		
_	Bready Controlling	T R s 12	1	
2.	Property Controlling in Section	S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		
	Property in Sec.	<u> </u>		
4.	Lot No	, Recorded Plat		
5.	Private Claims			

Register of Deeds Stamp & File Number

Paul R. Bressette, in a field survey on ____ <u>January 23 19 92</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - Section Corner common to Sections 1, 2, 11, and 12. Restored in 1956 by Billy Buckler, RLS. Set 1" iron pipe w/ 4" brass cap. 9" Cedar N 73° W 32 lks. 9" Cedar S 16° E 36 lks.
 - L-3. Quarter Corner common to Sections 1 and 2. 1959, origin unknown. Square 4" cedar post 3" Cedar N 15° E 6.25'; 4" Spruce S 62° E 12.48'; 4" Cedar S 10° E 14.60'. Found in DNR District 3 files of corners set by others.
- West one sixteenth Corner common to Sections 1 and 12. Not set in original survey, no evidence of subsequent establishment.
 Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found monument and witnesses as described. Both BT's alive and standing with blazes overgrown but visible. Rewitnessed monument as found.
 - L-3. Found 1/2" iron pin in concrete. Bearing and distance to above NBT's checks well. Corner also shown on plat of Tracy's Indian Bay Subdivision recorded in Liber C, p. 42 and 43. Distance to found plat monument checks closely.
 - Corner set midpoint and on-line between the Northwest and North Quarter corners of 1. Section 12.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 K-3. 1" iron pipe w/ 4" brass cap. 14" Cedar S 16° E 24.15' (old NBT); 14" Cedar N 77° W 20.9' (old NBT); 8" Cedar (S 1,NBT) N 53° E 7.4'; 4" Spruce (S 11,NBT) S 31° W 15.55'.
 - L-3. 1/2" iron pin in concrete. 7" Cedar ($\frac{1}{4}$ S,NBT) N 10° E 9.8'; 8" Cedar ($\frac{1}{4}$ S,NBT) S 40° E 17.95'; 5" Balsam ($\frac{1}{4}$ S,NBT) S 11° W 35.55'; 8" Cedar ($\frac{1}{4}$ S,NBT) N 62° W 23.9'.
 - DNR monument. 5" W. Birch (1/16,BT) N 87° E 7.8'; 8" Cedar (1/16,BT) S 43° W 17.5'; 10" cedar (1/16,BT) N 64° W 48.7'; 9" Ash (1/16,BT) N 03° W 45.9'. 1.

and R. R. Witter	Date	PAUL R. BRESSETTE LAND January 28 11 1992 SURVEYOR	1
Signed by	Date	No. FORM APPROVED BY MICHIGAN STATE MARCON, AND BITESTORS, JA REVISES	111