SURVEY & REMONUMENTATION

JAN 092001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menoritinee County
Land Survey Remonumentation
Peer Group Under Act 345 of PA. Of 1990 On 2000

Located in Comer Code # 1. Public Land Survey 755N p 25W p-69 1. Public Land Survey 755N p 25W p-69 1. RECEIVED FOR RECIRD 1. RECEIVED FOR RECIR	For corners in MENOMINEE	t mild trademaniate of the	/ 1, MICH. F.A.	13/0	Chairman	
2. Property Controlling S T R S Section S S T R S S S S S S S S S S S S S S S S	Loca	ated in: Corner Code #		Book	6 Page 18	' 7
2. Property Controlling S T R S Section S S T R S S S S S S S S S S S S S S S S	1. Public Land Survey	_T 35N _R 25W E-09				
2. Property Controlling S T R S S T R S Section S S S T R S S S S T R S S S S S S S S S	aana aana 24,73 ,			RE	CEIVED FOR RECORD	
2. Property Controlling STR R		TR				
3. Miscellaneous Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Register Register of Deeds Stamp & File Number Register Register Register of Deeds Stamp & File Number Register Register Register of Deeds Stamp & File Number Register R		_ TR			BARBARA MORRISON	
A Lot No	-	_ <u>T</u> R		Mi	ENOMINEE MI 49858	
4. Lot No	The state of the s	_ T_R				
William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 A. Description of original survey by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below In this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 c			_	Register of	Deeds Stamp & File Nur	nbe
William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 William Lenca In a field sprwy on June 26 A. Description of original survey by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below In this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 comera, as in the same town and range, may be recorded on this conflictate. NOTE: Not more than 2 c	4. Lot No , Recorded Pla	at				
William Lenca in a field survey on June 26 19 00 do hereby state that under requirements of P.A. 24 Michaen P.A. at 1970, the corner points mentioned in lines 1 and 2 above were in conformance with requisitions and rotes the Nove and Lend to the corner manual of survey instructions of the thickness that the corner points mentioned in lines 1 and 3 above were in nontrainable of survey instructions of the thickness of Lend to the the Corner manual of survey instructions of the thickness of the lines 2, and a show were in nontrainable of the survey instructions of the survey of the corner instructions of the survey of the corner instruction of the survey of the corner instructions of the survey of the corner instructions of the survey of the corner instructions of the corner instruction of the corner falls in the contentine of an East - West County Road and in line with an old fine tent the corner and instruction of the corner in the area, and with existing times of occupation, and is necepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessor	5. Private Claims			A B C D	E F G H I J K	L
William Lenca in a feet survey on June 26 1,000 do nearby state that under requirements of PA 74, Mohlgan PA, of 1970, the corner points medicined in lives 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of surveys refructions as the United States Department of the Indients, Pueuse of Land Management or by a descree of a Court of Law and for that the corner points mentioned in lines 3,4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveysro so by a Decree of a Court of Law, established, monumented, received, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N/20°E - 05 lks.; Birch, 8" - N/71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" x-rod was driven in blacktop read, replaced from measurements to fence corners as recorded by the Monominee Country Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" lincol not on the B.T.'s x W. Birch, 6" - N33°E - 79.12", Maple, 6" - S27°E - 43.70", W. Pinc, 12" - S33°W - 70.35"; Tamarack, 9" - N27°W - 61.07". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a fine fine and a commission of the corner falls in the centerfine of an East - West Country Road and in line with an old fence line North and the centerfine of a lane running South. This corner position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C. Description of monument for corner				2 - 6 - 5	4-3-2-	_ l
requirements of P.A. 24 Michael in a less survey on the corner points mentioned in lines 1 and 2 above were in conformance with requirements of the Interior, Burstey as equired in lines 1 and 2 above were in conformance with requirements of in lines 2, 4 and 5 above were in conformance with requirements of the Interior, Burstey and the Carrell manual of survey instructions of the Interior Burstey of Int	. William Lenca	June 26 00		3		_
controllance with regulations and rules between sequired in the current manual of survey instructions of the count of Lew and for United States Department of the letelor, Bureau of Land Management or by a decree of a Court of Lew and for that the corner points mentioned in times 3, 4 and 5 above were in conformance with the rules of the Michigan Surveyors or y a Decree of a Court of Lew, established, re-established, mortunented, found as expressed below. NOTE: Not more than 2 comens, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lbs.; Birch, 8" - N71°W - 06 lbs. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, R.L.S, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominer County Road Commission in 1949. 1993: Private records of William Lenca, R.L.S. No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Road & B.T.'s W. Birch, 6" - N33°E - 79.12", Maple, 6" - S27°E - 43.70"; W. Pinc, 12" - S53°W - 70.35"; Tamarack, 9" - N27°W - 61.07". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other cornerers in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the c	requirements of P.A. 74. Michigan P.A. of	1970, the corner points mentioned in lines 1	and 2 above were in		9-10-11-	—i¦2
natine context points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, mo	conformance with regulations and rules ther	refore as required in the current manual of sum	ev instructions of the	, 5 		\dashv
soard of Land Surveyrs or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Müllett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Metonine County Road Commission in 1949. 1999: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 56"x 24" Iron Road & B.T.'s W. Birch, 6" - N33°E - 79.12", Maple, 6" - S27°E - 43.70"; W. Pinc, 12" - S53°W - 70.35°; Tamarack, 9" - N27°W - 61.07". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box. 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box. 1970	that the corner points mentioned in lines 3.	, $f 4$ and $f 5$ above were in conformance with the $f i$	rules of the Michigan		7 16 15 14	13
NOTE: Not more than 2 comers, all in the same town and rangs, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Monominee County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Rod & B.T.'s: W. Birch, 6" - N33°E - 79.12", Maple, 6" - S27°E - 43.70"; W. Pinc, 12" - S53°W - 70.35", Tamarack, 9" - N27°W - 61.07". 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerfine of an East - West County Road and in line with an old fence line North and the centerfine of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. 6. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Al	Board of Land Surveyors or by a Decre	e of a Court of Law; established, re-establi	shed, monumented,	. 7		-
A. Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 17" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominee County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 576" x 24" fron Rod & B.T.'s: W. Birch, 6" - N33°E - 79.12'; Maple, 6" - S27°E - 43.70'; W. Pine, 12" - S53°W - 70.35'; Tamarack, 9" - N27°W - 61.07'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 578 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/2-1/4" dia. Alum. cap stamped for corner location in Monaument Box: 5/8" x 24" Iron Rod/2-1/4" dia. Alum. cap stamped for corner location in Monaument Box: 5/8" x 24" Iron Rod/2-1/4" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP "dia. Maple (Ex. B.T.) S57°W 70.35 feet Scr. NBT 14" dia. White Pinc (Ex. B.T.) N77°W 61.07 feet Scr. NBT NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. NOTE: All bearings are magnetic bea	•				$\frac{1}{1}$ $\frac{21}{1}$ $\frac{22}{1}$ $\frac{23}{1}$	2'4-
A Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, R.L.S, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominec County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 58" x 24" IRNR Od & B.T.'s: W. Birch, 6" - N33°E - 79.12", Maple, 6" - 827°E - 43.70"; W. Pine, 12" - S53°W - 70.35"; Tamarack, 9" - N27°W - 61.07". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP 7" dia. Maple (Bx B.T.) 14" dia. White Pinc (Ex, B.T.) 153°W 70.35 feet Scr. NBT 10" dia. Tamarack (Bx, B.T.) 10" dia. Tamarack (Bx	on this certificate.	the same town and range, may be record	ed			
A. Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by country road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominee Country Road Commission in 1949. 1933: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Rod & B.T.'s W. Birch, 6" - N33°E - 79.12'; Maple, 6" - S27°E - 43.70'; W. Pine, 12" - S53°W - 70.35'; Tamarack, 9" - N27°W - 61.07'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West Country Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP 7" dia. Maple (Ex. B.T.) S27°E 43.70 feet Scr. NBT 14" dia. White Pinc (Ex. B.T.) S33°W 70.35 feet Scr. NBT North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by All All All					28 - 27 - 26 -	—25-
A. Description of original monument and accessories and/or subsequent restoration: 1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominee County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Rod & B.T.'s: W. Birch, 6" - N33°E - 79.12'; Maple, 6" - S27°E - 43.70'; W. Pine, 12" - S53°W - 70.35'; Tamarack, 9" - N27°W - 61.07'. 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B. T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. 6. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" 8. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner loc					33 34 35	36
1848: Original Survey by James H. Mullett - B.T.'s - Birch, 8" - N20°E - 05 lks.; Birch, 8" - N71°W - 06 lks. All original evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominee County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Rod & B.T.'s: W. Birch, 6" - N33°E - 79.12'; Maple, 6" - S27°E - 43.70'; W. Pine, 12" - S53°W - 70.35'; Tamarack, 9" - N27°W - 61.07". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-						
evidence for this corner has been destroyed by county road improvements. 1970: L.C.R.C. No. 764, Volume 3, by Frank J. Bray, RLS, states that a 1/2" x 12" re-rod was driven in blacktop road, replaced from measurements to fence corners as recorded by the Menominee County Road Commission in 1949. 1993: Private records of William Lenca, RLS No. 26461, indicate that the corner described in LCRC No. 764, Vol. 3 was recovered and replaced with a 5/8" x 24" Iron Rod & B.T.'s: W. Birch, 6" - N33°E - 79.12'; Maple, 6" - S27°E - 43.70'; W. Pine, 12" - S53°W - 70.35'; Tamarack, 9" - N27°W - 61.07'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP 7" dia. Maple (Ex. B.T.) 52.7°E 43.70 feet Scr. NBT 14" dia. White Pine (Ex. B.T.) 52.5°E 43.70 feet Scr. NBT 10" dia. Tamarack (Ex. B.T.) N27°W 61.07 feet Scr. NBT North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.	A. Description of original monument a	and accessories and/or subsequent resto	oration:			
We recovered a 5/8 inch x 24 inch iron rod and 4 B.T.'s as described in my notes from a 1993 field survey. The corner falls in the centerline of an East - West County Road and in line with an old fence line North and the centerline of a lane running South. This corner position fits well with measurements to other corners in the area, and with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 7" dia. Maple (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) North North North North North North North North North Signed by L. L	1970: L.C.R.C. No. 764, Volum from measurements to fer 1993: Private records of William recovered and replaced with the control of the contro	ne 3, by Frank J. Bray, RLS, states that nce corners as recorded by the Menomi in Lenca, RLS No. 26461, indicate that ith a 5/8" x 24" Iron Rod & B.T.'s: W.	a 1/2" x 12" re-renee County Road	Commission in 1	949.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/2" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 7" dia. Maple (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Date June 30, 2000	B. Description of corner evidence fou	and and/or method applied in restoring or	reestablishing co	rner:		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP 7" dia. Maple (Ex. B.T.) S27°E 43.70 feet Scr. NBT 14" dia. White Pinc (Ex. B.T.) S53°W 70.35 feet Scr. NBT 10" dia. Tamarack (Ex. B.T.) Metal Survey Sign Post North North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by Date June 30, 2000	corner position fits well with meas	y Road and in line with an old fence lisurements to other corners in the area, a	ne North and the	centerline of a lar	ne running South. This on, and is accepted as the	A STATE OF THE STA
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" N57°E 51.29 feet 1' W. of PP 7" dia. Maple (Ex. B.T.) S27°E 43.70 feet Scr. NBT 14" dia. White Pinc (Ex. B.T.) S53°W 70.35 feet Scr. NBT N27°W 61.07 feet Scr. NBT North North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by W. W. W. of PP Tune 30, 2000					n -0	
7" dia. Maple (Ex. B.T.) 14" dia. White Pinc (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by W.	Set 5/8" x 24" Iron Rod/3-1/4" dia.	Alum. cap stamped for corner location	ı in Monument B	ox:	TOO LAND	(S)
7" dia. Maple (Ex. B.T.) 14" dia. White Pinc (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by W.	5/8" x 24" Iron Rod/2" dia. Alu	m. cap marked "WITNESS MARKER	" N570F	51 29 feet	1'W of DD	
14" dia. White Pinc (Ex. B.T.) 10" dia. Tamarack (Ex. B.T.) Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by White Pinc (Ex. B.T.) N27°W 61.07 feet Scr. NBT North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.	7" dia. Maple (Ex. B.T.)		S27°E			
Metal Survey Sign Post North 38.8 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by						
NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Signed by					Scr. NBT	
	NOTE: All bearings are magnetic	bearings. All distances are measured t	with steel tape. E		are to nail in side of tree.	
	Signed by (1), Winns 7		Data Ju	ne 30, 2000		
	Surveyor's Michigan License No.	26461			, , , , , , , , , , , , , , , , , , , 	