## SURVEY & REMONUMENTATION

JAN 0 9 2001

SECTION					App:	roved by d Survey	Menomine Remonum	B County
	LANI	D CORNER RECO	RDATION CERTIFI	CATE	Pe	er Group	Under Act	345 of
For corners in	Filir	Filing Requirement of Act 74, Mich. P.A. 1970			PA. 0f 1990 On 7/13, 2000			
MENOMINEE						Chairman		
(County)	Located In:	Corner Code #	<b>f</b>	$\mathcal{B}$	ook	6	Page	_ /73
1. Public Land Survey	T 35NR		5		<u></u>	· · · · · · · · · · · · · · · · · · ·		-
	TR TR				- [		R RECORD	
2. Property Controlling	TR S TR						10:16:09 (	7
in Section	<del></del>			I RE	ARBARA M GISTER O OMINEE	F DEEDS MI 49858		
Miscellaneous Property in Sec.	S TR					GITTIEL I	111 49000	
roperty in Occ.	5			Re	gister o	f Deeds	Stamp & f	ile Number
4. Lot No, Recon	rled Plat				,			
5. Private Claims	ucd i lat			A I	3 C I	EF	GHI	JKL
				2	 	5	3	_21
William Lenca		Oct 00		3		+		
William Lenca requirements of P.A. 74, Michiga	u r.a. di 1970 the come	er bointe montionad in lie	and I and I above were in	1	7— — { 	3		-1112
United States Department of the In	rules therefore as require nterior. Bureau of Land M	d in the current manual o	of survey instructions of the	5			++	
that the corner points mentioned Board of Land Surveyors or by	In lines 3. 4 and 5 above 1	Were in conformance with	h the rules of the Michigan	1 7	8 -1	7—16-	15-	-14 -13 
recovered, found as expressed bel	low:	- Law, Combioned, 16-6	salabilistica, monumentea,	81	92(	21_	22	-23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9				
on this certificate.				10—3	02	28-	27-	_2625-
				11				
				12 31	132	33_	<del>- 34 </del>	35 36- 
A. Description of original mon	nument and accessorie	es and/or subsequent	restoration;	13				
1991: L.C.R.C. No. 910 Section corners a	comer has been destr ), Book 3, by William nd midway between f	oyed by County Road Lenca, RLS No. 264 Sences running on No.	N43°W - 8 lks.; Beech d improvements. 461 states "Set 5/8" x 2 orth and South sides of 15.94'; Nail in 9" W. A	24" Iron F	Rod/Idea	nt. cap o	n line bety	veen
B. Description of corner evide	ence found and/or mel	thod applied in restori	ng or reestablishing cor	ner				
Found a 5/8 inch x 24 inch	n iron rod/Identificati	on cap and 4 B.T.'s i	in place as described in	a I. C R C	. No 9	10 (see r	nant All T	he
corner falls on line betwee South sides of and East - V occupation, and is accepted	n Section Corners 1/2 West County Road. T	2 mile North and 1/2 his position has beer	mile South and midw used as control for su	ay betwee	n old fa	ncec on	the North sting lines	and
C. Description of monument fo	or corner and accessor	ries established to per	petuate locating the po	sition of th	e corne		LERSCA LAND SURVEYO No. 20101	
Set 3/4" dia. x 4' long alum				SIGOTI OF III	e come	1. APP.	eped Last	SURVEY
							The state of the s	
5/8" x 24" Iron Rod/2" (E) 12" dia. White Ash	dia. Alum. cap marke victing B.T.)	ed "WITNESS MAR		47.54 fee			of 9" App	ole
9" dia. White Ash (Existing B.T.)			S62 <sup>o</sup> E S62 <sup>o</sup> W	16.91 fee 28.46 fee		Scr. NB Scr. NB		
20" dia. Black Ash (Ex Metal Survey Sign Post			N40°W	45.00 fee	et	Scr. NB		,
			South	2.5 feet				
NOTE: All bearings are m	agnetic bearings. Al	l distances are meast	ared with steel tape. D	oistances i	to trees	are to na	ail in side	of tree.
Signed by	Date N	ov. 16, 20	000					
Surveyor's Michigan License No	26461					<del></del>		
	~ <del>• • • • •</del>		<del></del>					