SURVEY & REMONUMENTATION

JAN 09 2001

.196	 حف یه	4 40	VL 60. I
9		4 6	11.6

Surveyor's Michigan License No.____

----26461-

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 of

SECTION	LAND COR Filing Req	LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 1			CATE PA Of 1990 On 7/3 2000				
For corners in				Boon		Page	121		
MENOMINEE	Located in:	Corner Code#		Door	૯	Page	176		
(County)				г					
1. Public Land Survey	T 35NR 26W	J-1	_		RECEIVED F	OR RECORD			
	TR		_	1	3 DEC 2000	IN IC.O.			
	ŢŖ	·			BARBARA A	1000100A			
2. Property Controlling	s _ TR		_		BARBARA M REGISTER C MENOMINEE,	F DEEDS			
in Section	S TR			<u> </u>	THE CONTRACT.	MI_49858			
3. Miscellaneous	s TR		_						
Property in Sec.	S TR		<u> </u>	Register	of Deeds St	amp & File N	lumber		
4. Lot No, Record	ed Plat			АВС	DEF	L. I H E	K L M		
5. Private Claims						1 1 2.			
SAME AS CORNER J-13,	T36N-R26W			3					
•		00		3		10-11	121		
, William Lenca requirements of P.A. 74, Michigan	in a field survey on	, 19VV d	o hereby state that under so 1 and 2 above were in	4	-				
				5					
				6 -18-	-1 7- 16	15-1-14	13		
United States Department of the in that the corner points mentioned in Board of Land Surveyors or by				7			24		
recovered, found as expressed belo	DW:	•		8 19	_2021	1 1)		
	ers, all in the same town and	rance, may be rec	corded	9	+++				
NOTE: Not more than 2 come on this certificate.	S16, Car 111 010 CC31110 12-111			10 30	2 ['] 92 ['] 8	2726	5		
				11	+++	1-1-1			
				12-31-	_3233	- 34 35	536		
				13					
A. Description of original mor	nument and accessories an	d/or subsequent	restoration:						
1848: Original Survey 1 evidence for this 1986: L.C.R.C. No. 740 marked MENON	by James H. Mullett - B.T corner has been destroyed 0, Book 3, by William Lendon MNEE COUNTY SURVE of accumulation to the East.	.'s - Cedar, 3" - 1 by County Road Ica, RLS No, 26 Y MARKER in " TIES: c/I Wh	N57°E - 17 lks.; Cedad improvements. 461 states "Set 30" lor centerline of County ite Birch 7", Scr. B.T.	ng Aluminum	Monument	with 4" cap	ited or.		
B.T., S48 ⁰ W, 50	0.24'; c/l Cedar 4", Scr. B	T., N5 ⁰ W, 40.5	5'.						
B Description of corner evid	dence found and/or method	l applied in restor	ing or reestablishing co	mer:					
		T. State C.D. C	No 740 (see part A	\ This corne	r falls in the	centerline o	fan		
Treet West County Road	d 3 B.T.'s in place as desc l and fits an old fence line ce of the position of the or	1/4 mue cast, n	as been used as contro	ol for surveys	in the area,	and is accep	tea as		
and dept arranged	-				TO THE	OF MICOS	AS .		
					THE TAY		WA B		
						WILLIAM	* # 8		
					*	LAND			
					1	Mo- STEASAOR			
						96461			
C. Description of monument	for corner and accessories	established to p	erpetuate locating the p	position of the	corner	Form and	Mark Co.		
	3-1/4" dia. Alum. cap star				***	CONTRACTOR OF LAND			
5" día, Tamarack	N34°E	55.31 feet	Scr. NBT						
5" dia, Tamarack 7" dia, Cedar	S48°E	68.9 feet	Scr. NBT						
9" dia. Tamarack	S38°W	68.14 feet	Scr. NBT						
7" dia. Elm	N46°W	49.88 feet	Scr. NBT				*		
Metal Survey Sign P	Post S04°E	29.4 feet					_		
	e magnetic bearings. All	distances are me	asured with steel tape			nail in side	of tree.		
Signed by 18), Mai	a Lun		Date	Aug. 8, 200	0				
Signed by /V // VIII	m charen								