## SURVEY & REMONUMENTATION

MAY 28 1997

## COMMISSION

5. Private Claims

LAND CORNER RECORDATION CERTIFICATE

Approved by Menominee Cour	itv
Tally Survey Remonumentation	M
Peer Group Under Act 345 0	1

•
•

For corners in	Filin	ng Requirement of Act 74, Mich	p. P.A. 1970	Chairman	KLS
MENOMINEE (County)	Located In:	Corner Code #		PAGE # 5 PAGE # 6 PAG	
1. Public Land Survey	B2N_R2 TR TR	25W <u>B07</u>		TANGE TO THE TANGE	
Property Controlling     in Section     Miscellaneous     Property in Sec.	TR S TR S TR S TR			MUDRI MN 8-45 PARISON OFFEDS 43888	
4. Lot No, Reco	orded Plat _	:	Regis	ster of Deeds Stamp & File Nu	mber

William Lenca \_, in a field survey on \_ Dec. 16, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

1	السار ا	<del> </del>		G H	IJ	KL
2	≥ <del> </del>	5-		3		
3	; <del> </del>	_  _	_ _ _			
` 4	├ <u>-</u>		9 <u>-</u>	10	<u> </u>	12_
5	<b> </b>  -		<u> </u>			
6	-18-	17-	16_	<del> </del> 15-	  14	13
7	-	-  -		11.		
8	19_	20	21	22	23	_24_
9			44-			
10	30	29	│	27	  26	_25_
11	<del>                                     </del>	-	┼-┼-			
12	—3 <u>1</u> —	32-	33_	34	35	<u> </u>
13			1			

A. Description of original monument and accessories and/or subsequent restoration:

Original Survey by George Adair - B.T.'s - Cedar, 14" - N70°E - 31 lks.; Cedar, 12" - S12°W - 18 lks. Found decayed 1852 stumps of both original B.T.'s in proper position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We computed the single proportional location for this corner, traversed in to it and searched the area. We found no evidence of the original B.T.'s or any old cedar stumps in this area. 89 feet North of this position is an ancient East - West fence line and 2 large Cedar stumps fitting the position of the original B.T.'s. The stumps are too decayed to determine markings, however the stumps are in proper position for the originals, cause the corner to fall on the ancient East - West fence line and within 2 feet of a proportional location for East - West position. We therefore accepted this location as a careful and faithful perpetuation of the position of the

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

6" dia. Yellow Birch 7" dia. White Ash 6" dia. White Ash 9" dia. Triple Maples (South tree) Metal Survey Sign Post	N51 <sup>0</sup> E S42 <sup>0</sup> E S38 <sup>0</sup> W N15 <sup>0</sup> W	17.90 feet 34.05 feet 20.53 feet 61.58 feet	Scr. NBT Scr. NBT Scr. NBT Scr. NBT
Metal Survey Sign Post	North	1.1 feet	SCr. NB



REVISED OCT., 199

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

$\sim \sim $		
Signed by William These	Dec. 26, 1996	•
Surveyor's Michigan License No26461	Date	