Approved by Menomines County Land Survey Remonumentation Peer Group Under Act 345 Of 990 On 12 199 ., 190 &

Filing Requir	rement of Ac	t 74, Mich. P.A. 1	970 Chairman	_
For corners in		1		
MENOMINEE Located In: Cor	ner Code #	1.	. 3 3 3 A	
(County)		- 35		
4 Bullio London or T. B		5-05	CONTROLLER	
1. Public Land Survey T <u>37N</u> R_25W T R		-	関係なら 二	
· ' <u></u> ' ' <u></u> ' 'R	-	_		
<u>; </u>		_	海道 💆 澤 - 潤	
2. Property Controlling ST_R			그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
in Section S TR			48 00 4 6	
3. Miscellaneous STR		_	01	
Property in Sec. S TR			Register of Deeds Stamp & File Numb	er
4. Lot No, Recorded Plat			ABCDEFGHIJK	L M
J. Fillage Classis			1	
			2 6 5 1 1 3 7 3	i
			3	-
l, William Lenca in a field survey on May				12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points me conformance with regulations and rules therefore as required in the cur-				+-
United States Department of the Interior, Bureau of Land Management	or by a decree o	f a Court of Law and /or	6 -19 -17 -16 -15 -14	13
that the corner points mentioned in lines 3, 4 and 5 above were in con Board of Land Surveyors or by a Decree of a Court of Law; esta			7	-├
recovered, found as expressed below:	20,00,000,000	ionale, manamonion	8 19 20 21 22 23	24—
NOTE: Not more than 2 comes of in the come town and made	a markaras	ordod	9	ļ
NOTE: Not more than 2 corners, all in the same town and rang on this certificate.	e, may be leco	lucu	10 30 29 28 27 26	 25
on the control of				_
			11 32 33 34 35	36
				1
A. Description of original monument and accessories and/or	etiheonijent të	etoration.	13	
7. Description of original mortalinaria and accessories disardi	,			
1852: Original Survey by George Adair - B.T.'s - He	emlock, 10" -	N520W - 07 lks.; C	edar, 10" - S470E - 19 lks. Original corner	
evidence was destroyed by county road improve		•		
1988: L.C.R.C. No. 808, recorded by William Lenca,				
road surface. Reset corner in centerline of Nor				
Rod/Ident. cap: Nail in Power Pole - N400E -	49.82"; 9" Ce	dar - S40°W - 42,73	"; 8" Ccdar - N34°W - 43.2".	
			~	
B. Description of corner evidence found and/or method appl	fed in restoring	or reestablishing co	rner:	
We recovered a 5/8 inch x 24 inch iron rod with a plast	ic identificati	on cap marked "MI	26461/WI 1569" in the centerline of a North	à
- South County Road and in line with an ancient fence				
808 matched the position of the existing iron rod. This				
accepted and used by local surveyors for several years, a	and is accepted	d as the best availab	le evidence of the position of the original	.,
corner.				
			of His	١.
			The state of the s	è <u>a</u>
			MAISIW *	* \$
•			# / LENCA	*
C. Description of monument for corner and accessories estab				*
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped	for corner loc	ation in Monument	Box: Ho. 26461	ંદુ
8" dia. Balsam N50°E	12 11 fant	Cor NIDT	E	÷.
	43.44 feet 70.85 feet	Scr. NBT Scr. NBT	FRED LAND S	150
· · ·	70.83 feet 42.73 feet	Scr. NBT	The state of the s	
	43.20 feet	Scr. NBT		
		y		
NOTE: All bearings are magnetic bearings. All distant	ces are measu	red with steel tape.	Distances to trees are to nail in side of tree.	
. Da		1	Dec. 23, 1996	
Signed by Ullam Fuce		Date		
Surveyor's Michigan License No. 26461				
				

425