SURVEY & REMONUMENTATION

APR 2 4 1995

Private Claims ___

expressed below:

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Approved by	Menominee County
Land Survey	Remonumentation
Peer Group	Under Act 345 Of

A AND AN ART AN AREA WAY SAFE OIL	
P.A. Of 1990 On DEC 16 100 4	
P.A. Of 1990 On 44C 16 100 4	
*** VI 1000 VII 35-5-6-7-6-199 7	
	_
Illa Dani Dic	


Filing Requirement of Act 74, Mich. P.A. 1970 ACTING For corners in

MENOMINEE Located In: Corner Code ## 1. Public Land Survey T _37N_ R _ 25W T ____ R ___ _ R __ R **Property Controlling** __ R. in Section _ R . Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

 William Lenca . in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

, Recorded Plat _

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



- Description of original monument and accessories and/or subsequent restoration:
 - 1847: Original Survey (Township Lines) by Henry Floyd - B.T.'s - Beech, 4"- N82°W, 07 lks; Beech, 6" - N75°E -07 lks. No original evidence found.
 - 1968: L.C.R.C. No. 680-Vol 3 by Frank J. Bray, DNR Surveyor, states that a 1" dia. Iron Pipe/4" dia. Alum. cap was set on line and midway between section corners to the east and west. New B.T.'s - 7" Ironwood - N35°E - 21-1/2 lks; 7" Basswood -N640W - 46 lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" dia. Iron Pipe/4" dia. Alum. cap and 2 Bearing Trees as described in part "A", in good condition. The corner position falls very nearly at the single proportionate position as intended in L.C.R.C. No. 680 - Vol. 3. We accepted the monument as a careful and faithful reestablishment of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Accepted existing 1"dia. Iron Pipe/3-1/4" dia. Alum. cap stamped for corner location:

9" dia. Ironwood - (Ex. B.T.)	N350E	14.43 feet	Scr. NBT
6" dia. Basswood	S73°E	12.52 feet	Scr. NBT
10" dia. W. Spruce	S48 ⁰ W	43.79 feet	Scr. NBT
12" dia. Basswood - (Ex. B.T.)	N64°W	30.36 feet	Scr. NBT
Survey Sign Post	M000M	1.7 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Nov. 15, 1994 Date_____ Surveyor's Michigan License No. ____

MAAN DW

ERED LAND