REMONUMENTATION

APR 2 4 1995

LAND CORNER RECORDATION CERTIFICATE

Pour (Proup Under Act 34	45 Of
PA DI 3000 Ga	DEC 16	1004
	ZEANI	
	2004011	

ed by Manominee County of Survey Remonumentation

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

۲O	or corners in			
	MENOMINEE	Located In:	Corner Code ##	
	(County)		Comer Code 44	
1.	Public Land Survey	T _37N_ R _25W T R T R T R	M-1	VED FOR C 27 / L V ARA MC STER OF
2.	Property Controlling in Section	S T R S T R		AM IO: 4 AM IO:
3.	Miscellaneous	S T R	i i	Register of Deeds Stamp & File Number
	Property in Sec.	S T R		Tregister of Deeds Stamp & File Humber
4.	Lot No,	Recorded Plat		A B C D E F G H I J K L
5.	Private Claims			
				2 6 5 4 3 7 2 6 7 1
				3
				4 - 7 - 8 - 9 - 10 - 11 - 12
			Oct 29 , 19 <u>94</u>	
			of 1970, the corner points mentioned	
		•	nd rules therefore as required in the rtment of the Interior, Bureau of Land	_1
		•	er points mentioned in lines 3, 4 and 5	1 1 1 1 1 1 1 1 1 1 1
			of Land Surveyors or by a Decree of a	
	ourt of Law; established, pressed below:	re-established, monumented, re-	monumented, recovered, found as	10 30 29 28 27 26 25
NC	OTE: Not more than 4	corners, all in the same town a	nd range, may be recorded	11
	on this certificate	. .		12 31 32 33 34 35 36
				13

- Description of original monument and accessories and/or subsequent restoration:
 - Original Survey (Township Lines) by Henry Floyd B.T.'s Hemlock, 24"- N55°W, 06 lks; Beech, 08" N72°E 41 lks. All original evidence for this corner has been destroyed by logging activities.
 - L.C.R.C. No. 689-Vol 3 by Frank J. Bray, DNR Surveyor, states that a 1" dia. Iron Pipe/4" dia. Alum. cap was replaced 1968: from a 3/4" dia. iron pipe with 2" ball on end. This pipe checks well with other corners in the area. No original evidence found. - New B.T.'s - 5" S. Maple - N31°W, 24 lks; 6" H. Maple - S61°E, 23.5 lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" dia. Iron Pipe/4" dia. Alum. cap set next to a 3/4" dia. iron pipe with 2" dia. ball on the end, and 2 Bearing Trees as described in part "A". Both DNR B.T.'s were found in good condition. We placed a nail in the sides of the existing B.T.'s and reused them. Since the DNR distances were to the face of the trees, our distances are slightly longer. This corner position fits well with corners to the west and south of this location. We accepted the DNR Monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the confi

Accepted existing 1"dia. Iron Pipe/3-1/4" dia. Alum. cap stamped for corner location:

10" dia. Maple	N57°E	32,28 feet	Scr. NBT
9" dia. Maple - (Ex. B.T.)	S61°E	15.62 feet	Scr. NBT
8" dia. Maple	S41°W	48.26 feet	Scr. NBT
8" dia. Maple - (Ex. B.T.)	N31oM	15.98 feet	Scr. NBT
Curron Cian Doct	NROOF	2 1 feet	



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Jane		15, 1994
	Date	
Surveyor's Michigan License No. 26461	FORM APPROVED BY MICHIGAN STATE B	BOARD OF LAND SURVEYORS, JAN. 28